

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Geiger, C. H. House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Geiger was president of North Central College from 1946-1960. House was featured in Naperville Heritage Housewalk Brochure.
<b>PERMITS</b>	Certificate of Rehabilitation issued January 2007.
<b>LANDSCAPE</b>	Northwest corner of Columbia and Benton; front and south sidewalks; side driveway; similar setbacks; mature trees; rear wood fence
<b>COA DATES</b>	1/4/2017; 5/19/2017
<b>COA DECISION</b>	COA #17-36 - In-kind window and siding replacement (approved 1/5/2017); COA #17-1941 - in-kind replacement of asphalt shingles (approved 5/23/2017)
<b>COA Compliance Notes</b>	COA-approved work does not appear to have been completed.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/13/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northeast corner of Columbia and Benton; front and south sidewalks; side driveway; similar setbacks; mature trees; front plantings
COA DATES	9/8/2009; 11/17/2016; 1/28/2021; 3/24/2022
COA DECISION	COA # 09-2172 - Replacement of front porch concrete steps (approved 9/8/2009); COA #16-4092 - recess entry door, rebuild and change dormer, create new entry and window openings, change several existing windows (approved by HPC 11/17/2016); COA #20-4723 - Carport attached to the primary structure (approved COA and recommended approval of variance 1/28/2021, Variance approved by CC 3/2/2021); COA #22-252 - New rear deck on corner lot, new ornamental fence on porte cochere, skylight (approved by HPC 3/24/22 with the condition that the pillars of the new deck be constructed of masonry to match existing elements of the residence)
COA Compliance Notes	
COA Work Not Completed	Work approved in COA #22-252 appears to have not been undertaken. Window replacement in south dormer (approved, COA #16-4092) also not undertaken.
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	Houghton, Walter E. House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	Folding doors replaced with overhead door on detached garage.



Work Completed Without COA

--

PREPARER	Lara Ramsey
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE	11/13/2025
SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear picket fence
COA DATES	3/21/2019
COA DECISION	COA #19-487 - alteration in front porch style (approved by HPC 3/21/2019)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	Siding painted.



**Work Completed Without COA**

Replacement windows on front façade

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; partial driveway; rear alley; similar setbacks; mature trees
COA DATES	8/13/2015
COA DECISION	COA #15-2811 - In-kind replacement of roof shingles (approved 8/14/2015)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

Removal of non-historic awnings from front façade-- may not require COA.

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	Umbreit, Franklin House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	7/30/2021; 4/6/2022
COA DECISION	COA #21-2777 - In-kind porch pillar and stairs replacement (approved 8/4/2021); COA #22-1096 - In-kind window replacement (approved 4/19/2022)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	Goehring, Louis and Verena House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southwest corner of Franklin and Columbia; front and north sidewalks; rear driveway; similar setbacks; mature trees; rear & south picket fence
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	Square oriel bay addition on first story of secondary south elevation.



**Work Completed Without COA**

--

PREPARER Lara Ramsey

SURVEYDATE 11/5/2007

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Residents (2007 survey )reported that two-toned brick was original feature of home; Sanborns also show brick veneer on exterior, with no indications of stucco/wood at 2nd story.

PERMITS

LANDSCAPE Southeast corner of Franklin and Columbia; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fencing

COA DATES 9/24/2020

COA DECISION COA #20-3635 - In-kind front porch stair replacement (approved 9/28/2020)

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="American Foursquare"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text" value="Queen Anne - Free Classic"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="c. 1905"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete - block"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text" value="Wood - shingle"/>	WINDOW MATERIAL	<input type="text" value="wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text" value="beveled glass"/>
WALL MATERIAL 2 (original)	<input type="text" value="Wood - shingle"/>	WINDOW TYPE	<input type="text" value="double hung/casement/fixed"/>
SIGNIFICANT FEATURES	<input type="text" value="Flared hipped roof with overhanging eaves; front &amp; side hipped dormers; full front porch with hipped roof, rounded columns &amp; square railings; wood shingle 2nd story (slight flare at 2nd story break); historic wood windows; 3-sided, 2-story south bay"/>		
ALTERATIONS	<input type="text" value="Replacement front steps (not historic); large 2 story rear addition, with 2nd south bay and rear porch (not historic). Post-2007 -- no changes."/>		

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS 1926 Sanborn Map shows building without rear addition.

LANDSCAPE Northeast corner of Columbia and Franklin; front and south sidewalks; rear alley; rear wood fence; similar setbacks; mature trees

COA DATES 12/29/2024

COA DECISION COA #24-3631 - a solid fence abutting a corner side yard on the property and is visible from a public street (approved by HPC 1/23/2025)

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

**Work Completed Without COA**

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fence

COA DATES 5/24/2018

COA DECISION COA #18-1491 - addition to rear that wraps around the front (withdrawn)

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA Aluminum double-hung replacement windows on first story on secondary north and south side elevations.

PREPARER Lara Ramsey

SURVEYDATE

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



Work Completed Without COA

11/19/2025

NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	6/24/2011;
COA DECISION	COA #11-2071 - Window replacement (approved 6/28/2011); COA #13-1360 - keep the south dormer (constructed without a COA) with modifications (approved by HPC 7/25/2013)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



<b>Work Completed Without COA</b>	
-----------------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	Heritage Place Building #9
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	This grouping of row houses is part of a larger residential development surrounding the P. E. Kroehler House.
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; mature trees in parkway; similar front setbacks; rear driveway
<b>COA DATES</b>	11/19/2019; 10/20/2020
<b>COA DECISION</b>	COA #19-2840 -- approval of demolition of properties on block (approved by City Council 11/19/2019); COA #20-2321 -- construction of town home units and rehab of Kroehler Mansion (denied by HPC, approved by City Council 10/20/2020 subject to administrative approval of revised plans for Heritage Place).
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	
<b>PREPARER</b>	Lara Ramsey
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/13/2025
<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE



<b>Work Completed Without COA</b>	
-----------------------------------	--

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Vocks, Herman House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; mature trees; similar setbacks
<b>COA DATES</b>	7/17/2015
<b>COA DECISION</b>	COA #15-2384 - In-kind replacement of front porch (approved 7/21/2015). City records state that the application was closed due to inactivity -- work may have been undertaken after COA expired.
<b>COA Compliance Notes</b>	Fascia board on replacement porch features square blocks above columns that were not present on previous porch -- design of porch as built falls within the "acceptable" guidelines for replacement porches outlined in the Historic Building Design and Resource Manual.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley and side driveway; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION

INTEGRITY

REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)

WINDOW MATERIAL

WALL MATERIAL 2 (current)

WINDOW MATERIAL

WALL MATERIAL (original)

WINDOW TYPE

WALL MATERIAL 2 (original)

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Open park district area planned as part of a larger residential development surrounding the P. E. Kroehler House.

PERMITS

LANDSCAPE

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

Work Completed Without COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

**Work Completed Without COA**

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

--

PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

**SIGNIFICANT FEATURES** Front jerkinhead roof with cornice returns; north and south jerkinhead gables; full front porch with hipped roof, round columns on solid knee wall; historic wood window with leaded glass upper sash under front porch south of entrance.

**ALTERATIONS** Post-2007 -- Aluminum siding replaced with fiber-cement board siding; solid knee walls on porch replaced with wood railings; replacement siding; Aluminum replacement windows in original openings.

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	6/23/2016; 8/25/2016
COA DECISION	COA #16-2362 - Replacement of aluminum siding with fiber cement siding & replacement of windows with aluminum clad windows (approved 6/24/2016); COA #16-2823 - change in porch style (tabled by HPC 8/4/2016, approved 8/25/2016)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION

INTEGRITY

REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

**Work Completed Without COA**

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Spreng, Bishop Samuel House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Subsequent owners of the house included Ben and Lucille Baumgartner Groves (1947-c. 1965); Burton and Patricia Ericson (1965-1985). Owners stated in house history questionnaire that they had been told the two homes directly north were built for family members of the owners of 146 N. Columbia Street. House featured in the February 4, 1960 edition of the Naperville Sun (page 1, section two).
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees
<b>COA DATES</b>	8/16/2012; 4/6/2022
<b>COA DECISION</b>	COA #12-2903 - Repair damaged roof, soffit and fascia (approved 8/20/2012); COA #22-1099 - In-kind window replacement (approved 4/19/2022)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	1/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="American Foursquare"/>	PLAN	<input type="text" value="Rectangular"/>
DETAILS	<input type="text" value="Craftsman"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="c. 1910"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete - block"/>
WALL MATERIAL (current)	<input type="text" value="Stucco"/>	PORCH	<input type="text" value="Front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Aluminum/Vinyl"/>
WALL MATERIAL (original)	<input type="text" value="Stucco"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/casement"/>
SIGNIFICANT FEATURES	<input type="text" value="Hipped roof with overhanging eaves and exposed rafter tails; front gable porch with square wood columns on concrete block piers; front hipped dormer"/>		
ALTERATIONS	<input type="text" value="Replacement windows in original openings (not historic); replacement front door (not historic); two story rear addition; replacement railing and steps on front porch (not historic). Post-2007 -- no changes."/>		

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; rear wood fencing; similar setbacks; mature trees
COA DATES	12/12/2011
COA DECISION	COA #11-4105 - Add railing for front porch stairs (approved 12/15/2011)
COA Compliance Notes	
COA Work Not Completed	Work approved by COA (COA #11-4105) appears to have not been undertaken.
Work Not Requiring COA	



**Work Completed Without COA**

--

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southeast corner of Columbia and School; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees
COA DATES	11/17/2017
COA DECISION	COA #17-4813 - In-kind replacement of asphalt shingles (approved 10/12/2017)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	Replacement door in south side secondary entrance opening



**Work Completed Without COA**

Replacement door to enclosed front porch (may be considered a storm door, which would not require COA)

PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northwest corner of Columbia and School; front and south sidewalks; rear driveway; rear fencing; similar setbacks; mature trees
COA DATES	5/26/2011
COA DECISION	COA #11-1157 - demolition of an existing staircase, awning and bracket to accommodate a new building addition, including enclosed porch on the rear (west) side of the home (approved by HPC 5/26/2011)
COA Compliance Notes	
COA Work Not Completed	Work approved by COA appears to have not been undertaken.
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="American Foursquare"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text" value="Prairie"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="1907"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Owner"/>	FOUNDATION	<input type="text" value="Parged"/>
WALL MATERIAL (current)	<input type="text" value="Stucco"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Stucco (over clay brick)"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/casement"/>
SIGNIFICANT FEATURES	<input type="text" value="Broad hipped roof with overhanging eaves; front hipped dormer; full width front porch with hipped roof, square stucco columns on solid knee walls, and curved frieze; historic 3/1 and 2-light wood windows"/>		
ALTERATIONS	<input type="text" value="1 story rear addition. Post-2007 -- no changes."/>		

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northeast corner of Columbia and School; front and north sidewalks; rear driveway/alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

3/1 replacement windows in original openings on front façade (historically compatible type and configuration); wrought iron railings at front steps replaced with painted wood railings

**PREPARER**

**ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

--

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; side driveway; similar setbacks; mature trees
COA DATES	8/26/2010; 1/25/2018
COA DECISION	COA#10-2177 - Replacement of siding with vinyl (denied by HPC 8/26/2010); COA #18-56 - Add two dormers, add shutters and brackets, repair the foundation base and vertical lattice, replace the stairs and railing system, replace three windows, put in wood siding and asphalt shingles, alter the front door (approved by HPC 1/25/2018)
COA Compliance Notes	Design of north and south dormers not consistent with design shown in exhibit included with COA approval.
COA Work Not Completed	
Work Not Requiring COA	Rear porch addition (pre-2018); replacement windows in altered openings on north and south secondary elevations (pre-2018)



**Work Completed Without COA**

--

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; rear alley; front sidewalk; rear picket fence; similar setbacks; mature trees
COA DATES	7/13/2023
COA DECISION	COA #23-1731 - Change in material for front porch walls and roof, change in style for front porch columns and the introduction of railings on the front porch stairs (approved by HPC 7/13/2023)
COA Compliance Notes	COA application (COA #23-1731) shows the existing stucco cladding remaining outside of the porch walls, section of front façade under porch, and front dormer.
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

Replacement windows on 2nd story of front façade (historically compatible type and configuration)

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Columbia and North; front and north sidewalks; rear driveway; similar setbacks; mature trees

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**  **SURVEYDATE**

**ORGANIZATION**  **SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	Attig, Jacob House
COMMON NAME	
ARCHITECT	
BUILDER	Fry, Oliver
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southwest corner of Columbia and North; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees
COA DATES	4/2/2012
COA DECISION	COA # 12-0862 - Roof replacement (approved 4/6/2012)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

--

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southwest corner of Columbia and Benton; front and north sidewalks; side driveway; similar setbacks; mature trees; rear picket fence
COA DATES	1/4/2017; 5/3/2019
COA DECISION	COA #17-36 - in-kind window and siding replacement (approved 1/5/2017); COA #19-1373 - In-kind replacement of porch columns (approved 5/6/2019)
COA Compliance Notes	Wood shingles replaced with fiber cement board siding.
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

Replacement front door.

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Sleight, William P. & Ida House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Southeast corner of Benton and Columbia; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees
<b>COA DATES</b>	12/12/2011; 9/8/2022; 7/2/2025; 10/16/2023
<b>COA DECISION</b>	See continuation sheet.
<b>COA Compliance Notes</b>	Escape window (#11-4104) not visible from public way.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

--

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/19/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE

**City of NAPERVILLE**  
ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

**STREET #**     8

**STREET**     S. COLUMBIA STREET

---

**ADDITIONAL PHOTOS OR INFORMATION**

*COA Decisions*

- COA #11-4104 - Replace escape window (approved 12/15/2011)
- COA #22-3731 - Removal of existing 4.5" reveal horizontal lap wood siding and 3.5" wood window trim. Installation of James Hardie Fiber Cement 5" reveal horizontal lap siding (approved 9/15/2022)
- HPC-0000-2025 - In-kind roof replacement with asphalt shingles (approved 7/8/2025)
- COA #23-3861 - two-story addition to a secondary façade that impacts the exterior architectural appearance of the primary façade of the principal structure and alters the roof shape and height (approved by HPC 10/26/2023)

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Sohl, Lawrence House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Chain of title for property from Naperville Heritage Society Address Files indicates house was built between 1905 & 1916.
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	Two-story rear addition that extends past south secondary elevation



**Work Completed Without COA**

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/13/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME** Schuler, Charles Royal House

**COMMON NAME**

**ARCHITECT**

**BUILDER** Kiest, Charles

**ARCHITECT SOURCE**

**HISTORIC INFO** According to history of house located in address files at Naperville Heritage Society, Charles Schuler and his wife were Chicago natives. Charles worked as an electrical engineer for Commonwealth Edison.

**PERMITS** Historic photos of house show that it was originally clad in stucco, with blind round arches above 1st story façade windows and round arch recessed front entry.

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear wood picket fence; similar setbacks; mature trees

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER** Lara Ramsey


**SURVEYDATE** 11/19/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE



**Work Completed Without COA**



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Gable Front"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="c. 1910-15"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete - block"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text" value="Aluminum"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/fixe"/>
SIGNIFICANT FEATURES	<input type="text" value="Front gable roof with cornice returns; north and south gable dormers; full front porch with square columns on solid knee wall; historic 1/1 and 1-light wood windows"/>		
ALTERATIONS	<input type="text" value="Replacement windows under front gable (not historic); window and door openings appear to have been altered under front porch (not historic). Post-2007 -- no changes."/>		

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

--

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO  
 Owner during 2007 survey may have had original plans--architect was supposedly a student of Frank Lloyd Wright; same house built on N. Julian

PERMITS

LANDSCAPE  
 Midblock on east side of residential street; front sidewalk; rear alley; rear picket fence; similar setbacks; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	1/27/2010
COA DECISION	COA #10-0148 - Window Replacement (approved 1/27/2010)
COA Compliance Notes	Two new windows placed on either side of existing window under porch on front façade.
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

Replacement railings at porch steps.

PREPARER	Lara Ramsey	SURVEYDATE	11/13/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	1926 and 1943 Sanborn Maps (sheets 7 and 12) show full width front porch on house.
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; rear chain link fence; similar setbacks; mature trees
COA DATES	5/27/2021
COA DECISION	COA 21-1720 - Addition and new front porch. Variance to the front setback for porch (HPC approved COA and recommended approval of variance 5/27/21. Variance approved by CC 6/15/21)
COA Compliance Notes	Work appears to be consistent with elevation drawings and site plan included in COA application.
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

3/1 Aluminum replacement windows on front elevation (do not match original 4/1 configuration, but are historically compatible)

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northwest corner of Columbia and Van Buren; front and south sidewalks; rear driveway; similar setbacks; mature trees
COA DATES	9/2/2009
COA DECISION	COA #09-2589 - Roof replacement (approved 9/2/2009)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO  Map of Sears-Roebuck Kit home locations in NHS file (called "Sears Homes") indicates that this is a kit home.

PERMITS

LANDSCAPE  Northeast corner of Columbia and Van Buren; front and south sidewalks; rear alley; large north side yard; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER  Lara Ramsey

SURVEYDATE  11/19/2025

ORGANIZATION  RAMSEY HISTORIC CONSULTANTS

SURVEYAREA  NAPERVILLE SURVEY UPDATE



**Work Completed Without COA**

Wood railing replaced with historically compatible new wood railing at front porch.

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL INDR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** During 2007 survey, Commission member stated that brick veneer was recently added (c. 1990-1995) and that building was original wood sided. Sanborn maps confirm that the building was originally wood frame.

**PERMITS**

**LANDSCAPE** Southwest corner of Columbia and Van Buren; front and north sidewalks; rear driveway; similar setbacks; mature trees

**COA DATES** 6/16/2022

**COA DECISION** COA #22-2105 - In-kind roof replacement (approved 6/23/2022)

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southeast corner of Columbia and Van Buren; front sidewalk; rear driveway; similar setbacks; mature trees
COA DATES	10/7/2009
COA DECISION	COA #09-3056 - Steps Repair (approved 10/7/2009)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

Aluminum replacement windows at east and west ends of north elevation (facing Van Buren Avenue)

PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; large north side yard; front sidewalk; rear alley; mature trees
COA DATES	8/26/2013
COA DECISION	COA #13-2992 - Demolition of an existing front porch and construction of a new wrap around porch on the west and south facades of the home (approved 8/26/2013)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO  
 Owner (2007) claimed that home underwent dramatic changes in the late 1930s. Sanborn maps from 1926 & 1943 show same massing, w/ 2 & 1-story wings. Porch is not shown on either map.

PERMITS

LANDSCAPE  
 Midblock on west side of residential street; large north side yard; front sidewalk; side driveway; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA  
 Detached garage replaced

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; mature trees; large (double) lot; rear wood fence
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

--

PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Prairie"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="c. 1915"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Stucco"/>
WALL MATERIAL (current)	<input type="text" value="Stucco"/>	PORCH	<input type="text" value="Front entry canopy"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="Double hung/awning"/>
SIGNIFICANT FEATURES	<input type="text" value="Broad hipped roof with overhanging eaves; south side hipped dormer; historic 3/1 wood windows &amp; 4-light awning windows; 1-story south sun porch"/>		
ALTERATIONS	<input type="text" value="One-story rear addition (historic); east side entry porch (post-1954). Post-2007 - no changes."/>		

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northwest corner of Columbia and Chicago; front and south sidewalks; rear driveway, privacy plantings; mature trees
COA DATES	5/28/2020
COA DECISION	COA #20-610 - addition, front and rear porch, cantilevered box bay window (approved by HPC 5/28/2020)
COA Compliance Notes	Work approved by COA does not appear to have been completed.
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

--

PREPARER	Lara Ramsey	SURVEYDATE	11/13/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE