

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Barr, Samuel house
COMMON NAME	
ARCHITECT	
BUILDER	Barr, Samuel
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northwest corner of Franklin and Ellsworth; front and south sidewalks; side driveway; similar setbacks; mature trees
COA DATES	9/28/2012
COA DECISION	COA #12-3641 - replacement of [north] side entry porch (approved 10/2/2012)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	Replacement windows on north secondary elevation
PREPARER	Lara Ramsey
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



Work Completed Without COA

2/2 double-hung replacement windows on front (east) façade and south elevation (facing Franklin Avenue) -- historically compatible type and configuration

11/20/2025

NAPERVILLE SURVEY UPDATE

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 105

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Historic Information

1892 Sanborn Map shows no front porch; 1898 map shows front entry porch. Current porch has no entry/steps.

From A GUIDE TO CHICAGO'S HISTORIC SUBURBS, p. 401:

“This clapboard farmhouse, built in 1874, has the massing and details reminiscent of Greek Revival, but with pedimented window heads characteristic of the 1870s date. Added at the turn of the century was the porch with its four, standard, Tuscan columns. The west end of the building has a porch from the same construction campaign and columns selected from the same catalogue, but with slightly different proportions.”

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; side driveway; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME Barr, Samuel House

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO House history questionnaire submitted by owner includes chain of title/ownership information and tax records. Title research indicates that the property was owned by Samuel Barr at the time the house was constructed.

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	8/20/2018;4/26/2019
COA DECISION	COA #18-3335 - Replacing door with window and in-kind replacement matching existing window (approved 8/22/2018); COA #19-1196 - remove window replace with door - door existed prior to 2018 (approved 4/26/2019)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	Replacement windows in original and altered openings on north and south secondary elevations; two-story rear addition



Work Completed Without COA

Replacement windows on front façade; north end enclosure of front porch evident in 2007 survey removed; cast-stone steps to front porch; wrought iron railings added above north and south knee walls at front porch.

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER


SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Leffler, Jeremiah House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	Naperville Historic District Website lists 129 N. Ellsworth as Jeremiah Leffler House, built in 1866. Building included in A GUIDE TO CHICAGO'S HISTORIC SUBURBS ON WHEELS AND ON FOOT, p. 401 (Naperville #6).
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
-----------------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO According to history of the house in Naperville Heritage Society address file, the house was built in 1872. See IHSS photograph for original massing of house. According to A GUIDE TO CHICAGO'S HISTORIC SUBURBS (p. 401-2), the south/rear addition was constructed in 1903 and featured a west-facing porch. The porch was removed when the large 2-story addition with corner tower was constructed in the 1990s.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; parking lot to south; similar setbacks; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR ROOF TYPE

DATESOURCE ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA



Work Completed Without COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Sporlein, Mary Elizabeth House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; low stone wall around lot; similar setbacks; mature trees
COA DATES	6/27/2016
COA DECISION	COA #16-2362 - In-kind replacement of front porch (approved 7/11/2016)
COA Compliance Notes	Porch structure does not appear to have been replaced, but porch railing is replacement.
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

Replacement windows on front façade.

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

City of NAPERVILLE
2025 HISTORIC RESOURCES SURVEY UPDATE
CONTINUATION SHEET

STREET # 135

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

According to Sanborn Maps, house was originally a one-story structure that has been altered and added to over the years: 1 story south side addition is historic, but south porch appears to have been altered (replacement posts, railing, and steps, Aluminum under eaves); second story addition to original house is historic; first story on north addition was added sometime between 1926 and 1949, with 2nd story added after; aluminum siding; replacement windows in altered openings (not historic--house originally had a full porch and entry on front façade); multiple rear additions; stone steps to north side entry and stone patio at front of house (not historic)

Post-2007 Alterations

Windows on front façade appear to be newer 1/1 aluminum replacement windows; porch railing replaced.

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS Sanborn maps (1909-1949) show a larger inset corner entry porch that extends across east end of façade

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATES 7/10/2018

COA DECISION COA #18-2732 - In-kind replacement of windows (approved 7/17/2018)

COA Compliance Notes 2007 survey photos show 1/1 double-hung windows on front and side elevations -- replacement windows are 2/2.

COA Work Not Completed

Work Not Requiring COA

PREPARER Lara Ramsey

SURVEYDATE

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



Work Completed Without COA

11/20/2025

NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	6/28/2012
COA DECISION	COA #12-2252 - Front steps replacement (approved 7/3/2012)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

Solar panels on roof--may have been present in 2007 and not noted on survey. 2007 survey photographs do not show slope of roof where panels are located.

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW TYPE

WALL MATERIAL 2 (original) WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; similar setbacks; mature trees
COA DATES	12/7/2018
COA DECISION	COA #18-4656 - In-kind shingle replacement in areas where small fire occurred (approved 12/10/2018)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Schwartz, Charles House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	See IHSS photograph for appearance of house before renovation. Featured on p. 402 of A GUIDE TO CHICAGO'S HISTORIC SUBURBS.
PERMITS	
LANDSCAPE	Southwest corner of Ellsworth and School; front and north sidewalks; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
-----------------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

City of NAPERVILLE
2025 HISTORIC RESOURCES SURVEY UPDATE
CONTINUATION SHEET

STREET # 151

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Recent renovation. Appropriate restoration work includes: replacement siding; replacement porch spindles and supports; replacement 1/1 windows; multi-light replacement windows on front bay; north entry porch; 1 story rear addition. Inappropriate alterations include glass block basement windows and a large 2-story addition to the south, including entry and porch, which is difficult to distinguish from the original massing of the home.

Post-2007 Alterations

No changes.

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southeast corner of School and Ellsworth; front and north sidewalks; picket fence; rear driveway; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northeast corner of School and Ellsworth; front and south sidewalks; rear alley; rear wood fence; large north side yard
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Helm, Daniel House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees

COA DATES 10/22/2020

COA DECISION COA #20-3281 - Made change without COA from brick to Bristol stone cast on the primary façade (denied by HPC on 10/22/20 and appeal denied by CC on 12/15/20)

COA Compliance Notes Stone at porch base remains in place.

COA Work Not Completed

Work Not Requiring COA Replacement windows on north and south secondary elevations; replacement door at ground-level south-side entry; entry porch and entrance toward rear of south elevation removed; replacement storm windows in porch

PREPARER Lara Ramsey

SURVEYDATE

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



Work Completed Without COA

Replacement windows on front façade

11/20/2025

NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear fence
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

--

PREPARER	Lara Ramsey
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE	11/20/2025
SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Patterson, William Henry House
COMMON NAME	
ARCHITECT	
BUILDER	McCorkel, Frank
ARCHITECT SOURCE	
HISTORIC INFO	Patterson, a farmer in Wheatland Township, had the home built after his retirement.
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear driveway; similar setbacks; mature trees; rear wood fencing
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
-----------------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW TYPE

WALL MATERIAL 2 (original) WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	Metal handrail added to steps on front porch
----------------------------	--

PREPARER	Lara Ramsey
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE	11/20/2025
SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Tax records research by Naperville Heritage Society indicate that house was probably built around 1873.

PERMITS Sanborn maps through 1949 show house with entry at front and no side porch.

LANDSCAPE Southwest corner of Ellsworth and North; front and north sidewalks; south side yard; rear driveway; mature trees

COA DATES 11/14/2017

COA DECISION COA #17-4764 - In-kind replacement of asphalt shingles (approved 11/14/2017)

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE



Work Completed Without COA 1/1 replacement windows in select openings on front façade and at west end of north elevation (facing North Avenue) at first story

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW TYPE

WALL MATERIAL 2 (original) WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southeast corner of North and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees
COA DATES	11/23/2016
COA DECISION	COA #16-4595 - In-kind shingle replacement (approved 11/28/2016)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

Single window at north end of front façade under porch replaced with paired Aluminum 1/1 double-hung windows.

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO
 Historic photograph of building on p. 37 of NAPERVILLE HOMECOMING (1917). Sanborn maps from as early as 1898 list building being used as a sausage factory.

PERMITS

LANDSCAPE
 Southeast corner of Ellsworth and Benton; front and north sidewalks; building comes to sidewalk; street parking; attached to building at 8 S. Ellsworth on S side

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	Owner indicated that the building was originally an ice house that was attached to 4-6 S. Ellsworth.
PERMITS	Sanborn Maps indicate that original 2 story building was extended south and east between 1898 and 1909--front porch, windows, and entry probably date from that time.
LANDSCAPE	Midblock on east side of residential street; attached to 4-6 S. Ellsworth on N. side; front sidewalk; rear alley; front planting
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	Paired window at north end of façade under front porch replaced with single 1/1 double-hung window.
-----------------------------------	---

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Building does not appear on 1869 Bird's Eye View of Naperville, but is present on the 1886 Sanborn Map. Sanborn maps also indicate that the full-front porch was constructed sometime between 1909 and 1921.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA Chimney on secondary south elevation demolished.

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

Aluminum/vinyl replacement windows on 2nd story of front façade

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR ROOF TYPE

DATESOURCE ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps indicate that the building was converted into a duplex sometime between 1921 and 1926.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; large south side yard; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION

INTEGRITY

REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Side yard associated with 16 S. Ellsworth Street.

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

Work Completed Without COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR ROOF TYPE

DATESOURCE ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Metz, Adam House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	Chain of title indicates Metz purchased property from Alvin Scott in 1874 for \$440. Inventory of Metz estate date 1878 makes mention of house.
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; rear and side picket fence; large south side yard; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	Former site of late 19th century Greek Revival residence rated "C" in 2007 survey. Historic maps indicate that the building was likely constructed early 1870s.
PERMITS	
LANDSCAPE	Northeast corner of S. Ellsworth and Van Buren; front and south sidewalks; rear/south picket fence; rear alley; oversized lot; mature trees
COA DATES	5/6/2016; 1/26/2012
COA DECISION	COA #15-3111 - Addition of 2 upper story windows, modifying screen porch to windows (approved 3/28/2016); COA #11-2993 - demolition of the existing structure and new construction (approved by HPC 1/26/2012); COA #13-3320 - Modifications to the site plan and Building Elevations approved through COA #11-2293 (approved by HPC 9/26/2013); COA #15-3111 - construction of new residence (tabled by HPC 9/24/2015, approved 10/29/2015)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
-----------------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southeast corner of Van Buren and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

--

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps indicate that the house was constructed sometime between 1949 and 1954.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; similar setbacks; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

1/1 replacement windows on attic level and in front dormer.

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Aerial photographs indicate that the center entry porch was constructed sometime between 1978 and 1987.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps indicate the house originally featured a two-story north wing with a one-story west-facing porch, which was removed sometime between 1921 and 1926.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATES 5/18/2018

COA DECISION COA #18-1902 - In-kind replacement of windows (approved 5/23/2018)

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES Front gable roof with wide wood frieze; south polygonal window bay with segmental arch windows, narrow round arch wood panels, carved brackets, and paneled frieze; 2/2 wood windows with flanged pediment lintels; recessed entry with paneled sides & transoms; historic double wood doors (altered)

ALTERATIONS Solid arched glass panes in front doors were probably originally wood (not historic); replacement front and south/rear porches (historic); concrete front steps with wrought iron railing; 1 story north/rear addition (historic). Post-2007 -- replacement asphalt-shingle roof.

HISTORIC INFORMATION

HISTORIC NAME	Stenger, Elizabeth House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	History provided by owner during 2007 survey.
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	4/19/2020
COA DECISION	COA #20-831 - In-kind shingle replacement (approved 4/23/2020)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
-----------------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Feldott, Ralph House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	lot was originally part of 126 S. Ellsworth, according to owner (2007 survey)
PERMITS	
LANDSCAPE	midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
-----------------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE