ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	621				
DIRECTION	E		\wedge	E. ale to	
STREET	BENTON		1		
SUFFIX	AV				
PIN	0818403006				
LOCAL SIGNIFICANCE RATING POTENTIAL IND NR? (Y or N)	CN		62 ₁		
Contributing to a NR DISTRICT? Contributing secon Listed on existing SURVEY?	C dary structure? C Local District; NR District				
GENERAL INFORMATION					
CATEGORY bu	uilding	CURRENT FUNCTIO	N Domestic - single dwell	ling	
CONDITION ex	cellent	HISTORIC FUNCTIO	N Domestic - single dwell	ling	
INTEGRITY m	inor alterations and addition(s)	REASON for SIGNFICANCE			
SECONDARY STRUCTURE	Detached garage				
ARCHITECTURA		ARCHITECTURAL	DESCRIPTION		
ARCHITECTURA			— DI AN	rectangular	

ARCHITECTURA CLASSIFICATION	-	Bungalow		PLAN	rectangular
		5		NO OF STORIES	1.5
DETAILS				ROOF TYPE	Side gable
BEGINYEAR	c. 1920			ROOF MATERIAL	Asphalt - shingle
OTHER YEAR					
DATESOURCE	Surveyor			FOUNDATION	Concrete - block
WALL MATERIA	I (current)	Wood		PORCH	Front
	. ,	11000		WINDOW MATERIA	L Aluminum/wood
WALL MATERIA	L 2 (current)			WINDOW MATERIA	L Leaded glass
WALL MATERIA	L (original)	Wood		WINDOW TYPE	double hung/fixed
WALL MATERIA	L 2 (original)				
				WINDOW CONFIG	1/1; 1-light; multi-light
	0		ckets; original front porch structur ass upper sash	e with front gable roof an	d rafter tails; historic single

ALTERATIONS Original front porch enclosed with picture window (1950s, non-historic); new front porch added at corner (nonhistoric); rear dormer addition; 1/1 replacement windows in original openings (non-historic)

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on north side of residential street; front sidewalk; rear driveway & alley; similar setbacks; mature trees; east side yard enclosed with picket fence





COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
621 E BEN'	TON

DIGITAL PHOTO ID	\I 2
DIGITAL	\I
PHOTO ID2	2

)	\Images\benton6 21e.jpg	DIGITAL PHOTO ID3
02	\Images\benton6 21e(2).jpg	DIGITAL PHOTOID4

\Image 3).jpg	s\benton621e(
\lmage 4).jpg	s\benton621e(

STREET #	06				
DIRECTION			* York		
STREET	BENTON		N N ALAC		
SUFFIX	١V	the second s			
PIN					
LOCAL SIGNIFICANCE RATING)				
POTENTIAL IND NR? (Y or N)	l				
Contributing to a NR DISTRICT?					
Contributing seconda Listed on existing SURVEY?	ry structure? NC				
GENERAL INFORMATION					
CATEGORY build	ling	CURRENT FUNCTIO	N Domestic - multiple dw	velling	
CONDITION good	d	HISTORIC FUNCTIO	N Commerc/Trade/Dome	estic - single dwelling	
INTEGRITY mind	or alterations and addition(s)	REASON for SIGNFICANCE			
SECONDARY STRUCTURE	Detached garage				
		ARCHITECTURAL	DESCRIPTION		
ARCHITECTURAL CLASSIFICATION	No style		PLAN	Rectangular	
DETAILS			NO OF STORIES	2	
	c. 1910		ROOF TYPE	Side gable	
BEGINYEAR OTHER YEAR	C. 1910		ROOF MATERIAL	Asphalt - shingle	
DATESOURCE	Surveyor		FOUNDATION	Stone	
WALL MATERIAL			PORCH	Side	
WALL MATERIAL	```		WINDOW MATERIA	AL Wood	
WALL MATERIAL			WINDOW MATERIA		
WALL MATERIAL	-		WINDOW TYPE	double hung/fixed	
			WINDOW CONFIG	1/1; 1-light	
SIGNIFICANT 2r FEATURES	nd story square projecting win	dow bay on north elevation w	ith hipped roof with overha	anging eaves;	
	nborn maps indicate that the ilding at 4-6 S. Ellsworthrep			dation of an early addition to orch addition (may be historic)	

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	



SOURCE	
HISTORIC INFO	
PERMITS	See attached Sanborn maps.
LANDSCAPE	E Midblock on south side of residential/college street; front sidewalk; house built to lot line; rear alley and parking

COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
206 E BEN	TON

DIGITAL PHOTO ID	
DIGITAL PHOTO ID2	

)	\Images\benton2 06e.jpg	DIGITAL PHOTO ID3
02	\Images\benton2 06e(2).jpg	DIGITAL PHOTOID4

\Images\benton206e(3).jpg
\Images\benton206e(4).jpg

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

DIRECTIONESTREETBENTONSUFFIXAVPIN0818314001LOCAL SIGNIFICANCE RATINGCPOTENTIAL IND NR? (Y or N)NContributing to a NR DISTRICT?C						
SUFFIX AV PIN 0818314001 LOCAL SIGNIFICANCE RATING C POTENTIAL IND NR? (Y or N) N						
PIN 0818314001 LOCAL SIGNIFICANCE RATING C POTENTIAL IND NR? (Y or N) N						
LOCAL SIGNIFICANCE RATING C POTENTIAL IND NR? (Y or N) N Contributing to a						
SIGNIFICANCE RATING C POTENTIAL IND NR? (Y or N) N Contributing to a Image: Contributing to a						
NR? (Y or N) N Contributing to a						
Contributing to a NR DISTRICT?						
Contributing to a NR DISTRICT? C Contributing secondary structure? C						
Listed on existing						
SURVEY? Local District; NR District						
GENERAL INFORMATION						
CATEGORY building CURRENT FUNCTION Domestic - single dwelling						
CONDITION good HISTORIC FUNCTION Domestic - single dwelling						
INTEGRITY minor alterations and addition(s) REASON for SIGNFICANCE						
SECONDARY Detached garage						
ARCHITECTURAL DESCRIPTION						
ARCHITECTURAL CLASSIFICATION American Foursquare PLAN Rectangular						
DETAILS NO OF STORIES 2.5						
BEGINYEAR C. 1915 ROOF TYPE Hipped						
OTHER YEAR Asphalt - shingle						
OTHER YEAR ROOF MATERIAL Asphalt - shingle DATESOURCE Surveyor Parged						

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

SIGNIFICANT FEATURES

Hipped roof with overhanging eaves and front central hipped dormer; front porch with square piers on solid knee walls (enclosed); square north window bay; leaded glass casement windows; historic 3/1 and 2-light wood windows

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

Wood

Leaded glass

3/1; 1-light; 2-light

Dbl hung/casement/awnin

ALTERATIONS Front porch enclosed (historic)

Stucco

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	2
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Alternate Address6 S. Loomis. Southeast corner of Benton and Loomis; front and north sidewalks; rear driveway; similar setbacks; mature trees; rear wood fence



COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
212 E BEN	TON

DIGITAL	\lmaq
PHOTO ID	06s.j
DIGITAL	∖lma
PHOTO ID2	06s(2

)	\Images\loomis0 06s.jpg	DIGITAL PHOTO ID3
02	\Images\loomis0 06s(2).jpg	DIGITAL PHOTOID4

\Images\loomis006s(3).jpg
\Images\loomis006s(4).jpg

STREET #	224			antala s			50 50	
DIRECTION	E							
STREET	BENTON		-					CALL THE
SUFFIX	AV		-		The second		R. Fr	
PIN	0818314007			Elin	1			
LOCAL SIGNIFICANCE RATING POTENTIAL IND NR? (Y or N) Contributing to a NR DISTRICT? Contributing secon Listed on existing SURVEY?	C N C dary structure Local District;							
GENERAL INFORMATION								
CATEGORY bu	uilding			CURRENT FUNCTIO	ON [Domestic - multiple dw	ellin	g
CONDITION Good/fair HISTORIC FUNCTION Domestic - single dwelling								
INTEGRITY minor alterations and/or addition(s) REASON for								
SIGNFICANCE SECONDARY STRUCTURE								
			AR	CHITECTURAL	L DI	ESCRIPTION		
ARCHITECTURA CLASSIFICATION						PLAN	Re	ctangular
DETAILS	,					NO OF STORIES	2	
BEGINYEAR	c. 1915					ROOF TYPE	Sic	de gable
OTHER YEAR	0. 1010					ROOF MATERIAL	As	phalt - shingle
DATESOURCE	Surveyor					FOUNDATION	Co	ncrete - block
WALL MATERIA		Wood				PORCH	Wr	ap around
WALL MATERIA						WINDOW MATERIA	L	Wood
WALL MATERIAL 2 (current) WINDOW MATERIAL WINDOW MATERIAL WOOD								
WALL MATERIA	-					WINDOW TYPE		double hung/casement
						WINDOW CONFIG		1/1; 5-light
SIGNIFICANT FEATURES	Three-sided, tv	vo story east side	bay; v	wraparound front porc	h (pa	rtially enclosed)		
						porch partially enclose istoric); balustrade at p		ith 5-light wood windows h roof (not historic)

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on south side of residential street; front sidewalk; west alley; similar setbacks; mature trees



COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
224 E BEN ⁻	TON

DIGITAL	\
PHOTO ID	2
DIGITAL	\
PHOTO ID2	2

)	\Images\benton2 24e.jpg	DIGITAL PHOTO ID3
2	\Images\benton2 24e(2).jpg	DIGITAL PHOTOID4

\Images\benton224e 3).jpg	;(
\Images\benton224e 4).jpg	;(

City of NAPERVILLE ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 310

STREET E. BENTON AVENUE

ADDITIONAL PHOTOS OR INFORMATION

Red brick exterior with block brick corner quoins and frieze; projecting front bay with stone pediment and fluted pilasters w/ Corinthian capitals; stone round and rectangular decorative carved panels; 3 front entries with decorative stone surrounds; stone surrounds at windows above entries; brick east and west square pilasters with stone tiled bays between; historic stained glass windows

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	310		
DIRECTION	E		
STREET	BENTON		
SUFFIX	AV		
PIN	0818315001-002	THE DISTURS FROM THE OFFICER TO THE	
LOCAL SIGNIFICANCE RATING POTENTIAL IND NR? (Y or N)	S N		
Contributing to a NR DISTRICT? Contributing second Listed on existing SURVEY?	C dary structure? -		

GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	DN Education - college
CONDITION	excellent	HISTORIC FUNCTION	ON Education - college
INTEGRITY	minor alterations	SIGNFICANCE	Impressive Classical Revival building featuring pedimented front entry bay with fluted pilasters and classical detailing.
SECONDARY STRUCTURE			


ARCHITECTURAL DESCRIPTION

ARCHITECTURA	L		DIAN	irregulor
CLASSIFICATIO	N Classical	Revival	PLAN	irregular
			NO OF STORIES	3
DETAILS			ROOF TYPE	Flat
BEGINYEAR	1925		KOUF TYPE	Flat
			ROOF MATERIAL	Not visible
OTHER YEAR			- FOUNDATION	Not visible
DATESOURCE	Cornersto	one	FOUNDATION	
			PORCH	-
WALL MATERIA	L (current)	Brick	WINDOW MATERIAL	L Wood/Vinyl
WALL MATERIAL 2 (current)		Stone		
·····			WINDOW MATERIAL	L Stained glass
WALL MATERIAL (original)		Brick	WINDOW TYPE	double hung
WALL MATERIAL 2 (original)		Stone		
			WINDOW CONFIG	6/6; multi/multi
	D 11 1 1			
		rior with block brick corner quoins and frieze; pro		
FEATURES	pliasters w/ Co	rinthian capitals; stone round and rectangular de	corative carved panelsc	SEE CONTINUATION SHEET
r				

ALTERATIONS Replacement doors; replacement windows in rear bay; wrought iron railing at front steps

HISTORIC	Pfeifer, Barbara Memorial Hall
NAME	
COMMON NAME	
COST	
ARCHITECT	Llewellyn, Joseph & Ralph
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	NHS Brochure (East)
HISTORIC FINFO	art of North Central College
PERMITS	
LANDSCAPE	Alternate address is 10 S. Brainard. Southeast corner of Benton and Brainard; front and west sidewalks; east alley; mature trees





DIGITAL	\\
PHOTO ID	1
DIGITAL	\
PHOTO ID2	1

)	\Images\benton3 10e.jpg	DIGITAL PHOTO ID3
02	\Images\benton3 10e(2).jpg	DIGITAL PHOTOID4

\Image 3).jpg	s\benton310e(
\Image 4).jpg	s\benton310e(

STREET #	325	*			
DIRECTION	E				
STREET	BENTON	H-			
SUFFIX	AV	1 Station	Sec. 1		
PIN	0818306001	1			
LOCAL SIGNIFICANCE RATING POTENTIAL IND NR? (Y or N)	NC				
Contributing to a NR DISTRICT? Contributing secon	Contributing to a NR DISTRICT? NC Contributing secondary structure? -				
Listed on existing SURVEY?	Local District; NR District	-			
		GENERAL INFOR	MATION		
CATEGORY bu	uilding	CURRENT FUNCTION	Education - college		
CONDITION ex	cellent	HISTORIC FUNCTION	Education - college		
INTEGRITY no	ot altered	REASON for SIGNFICANCE			
SECONDARY STRUCTURE	-				
		ARCHITECTURAL I	DESCRIPTION		

		11		
ARCHITECTURAL CLASSIFICATION	Internatio	nal Style	PLAN	rectangular
DETAILS			NO OF STORIES	2
	4000		ROOF TYPE	Flat
BEGINYEAR	1960		ROOF MATERIAL	Not visible
OTHER YEAR			FOUNDATION	Concrete - poured
DATESOURCE	Plaque			
WALL MATERIAL (cu	(rrent)	Brick	PORCH	-
			WINDOW MATERIA	L Metal
WALL MATERIAL 2 (current)	Concrete	WINDOW MATERIA	r [
WALL MATERIAL (or	riginal)	Brick		
(0	-8)		WINDOW TYPE	Fixed/awning
WALL MATERIAL 2 (original)	Concrete - block		5
	0 /		WINDOW CONFIG	1-light; multi-light
				<u> </u>

SIGNIFICANT FEATURES	
ALTERATIONS	

HISTORIC NAME	
COMMON NAME	White Activities Center
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
	Northwest corner of Loomis and Benton; front and east sidewalks; rear parking lot; similar setbacks; mature trees



COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
325 E BEN	TON

DIGITAL	\lmages
PHOTO ID	25e.jpg
DIGITAL	\Images
PHOTO ID2	25e(2).j

D	\Images\benton3 25e.jpg	DIGITAL PHOTO ID3
D2	\Images\benton3 25e(2).jpg	DIGITAL PHOTOID4

\lmage 3).jpg	s\benton325e(
\Image 4).jpg	s\benton325e(

STREET #	415			
DIRECTION	E	No. A.		, ANA
STREET	BENTON			
SUFFIX	AV			
PIN	0818310004	A ANE NOT		
POTENTIAL IND	S			
Contributing to a NR DISTRICT? Contributing second	c			
		GENERAL INFO	DRMATION	
CATEGORY bu	lding	CURRENT FUNCTION	ON Domestic - single dwel	ling
CONDITION	cellent	HISTORIC FUNCTION	ON Domestic - single dwel	ling
INTEGRITY mit	nor alterations		This bungalow was original ticket booth in Burlington Pa	
SECONDARY STRUCTURE	Detached garage			ark.
	A	ARCHITECTURAI	L DESCRIPTION	
ARCHITECTURAI CLASSIFICATION	, Bungalow		PLAN	Rectangular
			NO OF STORIES	1.5
DETAILS	Prairie		ROOF TYPE	Hipped
BEGINYEAR	c. 1915		ROOF MATERIAL	Asphalt - shingle
OTHER YEAR	1927		FOUNDATION	Concrete - block
DATESOURCE	NHS Walking Tour Brochure		PORCH	Front
WALL MATERIAI			WINDOW MATERIA	L Wood
WALL MATERIAI			WINDOW MATERIA	
WALL MATERIAI			WINDOW TYPE	Double hung/sliding
WALL MATERIAI	2 (original) Wood - shingle		WINDOW CONFIG	2/2; 1-1
	ared hipped roof with overhanging ood windows	g eaves; front porch with	flared roof and curved oper	nings; historic 2/2 vertical
	uilding moved to current location b ddition (historic); vinyl siding unde			rn Maps)front porch

HISTORIC NAME	Burlington Park Ticket Booth
NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT	2
BUILDER	
ARCHITECT SOURCE	
INFO	According to NHS, this building was originally the boat rental office in Burlington Park. The park closed in 1899. See attached research.
PERMITS	
LANDSCAPE	Midblock on north side of residential street; front sidewalk; east alley; similar setbacks; mature trees



COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
415 E BEN	TON

DIGITAL	\li
PHOTO ID	1
DIGITAL	\
PHOTO ID2	1

)	\Images\benton4 15e.jpg	DIGITAL PHOTO ID3
02	\Images\benton4 15e(2).jpg	DIGITAL PHOTOID4

\Images\benton41 3).jpg	5e(
\Images\benton41 4).jpg	5e(

STREET #	416				
DIRECTION	E	Y.			ST PROVING
STREET	BENTON				
SUFFIX	AV		A SWW		
PIN	0818316002		A A A A A A A A A A A A A A A A A A A		
LOCAL SIGNIFICANCE RATING	С				
POTENTIAL IND NR? (Y or N)	Ν				
Contributing to a NR DISTRICT? Contributing secon Listed on existing	C dary structure	? C			
SURVEY?	Local District;	NR District			
			GENERAL INFO	RMATION	
CATEGORY bu	uilding		CURRENT FUNCTIO	DN Domestic - single dwe	lling
CONDITION ex	cellent		HISTORIC FUNCTION	ON Domestic - single dwe	lling
INTEGRITY m	ajor alterations	and/or addition(s)	REASON for		
SECONDARY STRUCTURE	Detached gar	age	SIGNFICANCE		
			 ARCHITECTURAI	DESCRIPTION	
ARCHITECTURA CLASSIFICATION				PLAN	rectangular
	N Gable Fro	m		NO OF STORIES	2.5
DETAILS				ROOF TYPE	Front gable
BEGINYEAR	c. 1910			ROOF MATERIAL	Asphalt - shingle
OTHER YEAR				FOUNDATION	Concrete - block
DATESOURCE	Surveyor/			PORCH	Full front
WALL MATERIA		Wood		WINDOW MATERIA	AL Wood
	WALL MATERIAL 2 (current) Wood - shingle WINDOW MATERIAL				
WALL MATERIA	-	Wood		WINDOW TYPE	double hung
WALL MATERIA	L 2 (original)	Wood - shingle		WINDOW CONFIG	6/6; 4/4; 6/1
		of; historic window o toric 4/4 wood wind		cal lintels; front porch with c	classical columns on concrete
	Replacement s addition	siding (not historic);	replacement 6/6 and 6/1	wood windows in original o	openings (historic); 2 story rear

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
PERMITS	House first appears on 1921 Sanborn Map (not shown on 1909 map).
LANDSCAPE	Midblock on south side of residential street; front sidewalk; east alley; west side driveway; similar setbacks; mature trees; rear/west fence



COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
416 E BEN	TON

DIGITAL	\I
PHOTO ID	1
DIGITAL	\I
PHOTO ID2	1

)	\Images\benton4 16e.jpg	DIGITAL PHOTO ID3
2	\Images\benton4 16e(2).jpg	DIGITAL PHOTOID4

\Images\benton410 3).jpg	6e(
\Images\benton410 4).jpg	6e(

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	510		land and		_~/ 7#			X X 15
DIRECTION	E				1 th		0	
STREET	BENTON			Z A	D	A AA	X	The setter .
SUFFIX	AV		1		The h	1 A	K	
PIN	0818317001						-	
LOCAL SIGNIFICANCE RATING	С							
POTENTIAL IND NR? (Y or N)	Ν			NI FFF	I			The last
Contributing to a NR DISTRICT?	С				-		10	
Contributing secon	dary structure?	C			125	EAL BLA		
Listed on existing SURVEY?	Local District;	NR District	the second					
			<u>G</u>	ENERAL INFO	ORN	<u>IATION</u>		
CATEGORY b	uilding		C	CURRENT FUNCTI	ON	Domestic - single dwelli	ng	
CONDITION ex	kcellent		H	HISTORIC FUNCTI	ON	Domestic - single dwelli	ng	
INTEGRITY	inor alterations	and addition(s)		REASON for SIGNFICANCE				
SECONDARY STRUCTURE	Detached gara Shed (NC)	age						
			ARC	CHITECTURA	L D	ESCRIPTION		
ARCHITECTURA CLASSIFICATION						PLAN	irre	egular
DETAILS						NO OF STORIES	2	
BEGINYEAR	c. 1910					ROOF TYPE	Hip	pped
OTHER YEAR	0. 1910					ROOF MATERIAL	As	phalt - shingle
DATESOURCE	surveyor					FOUNDATION	Sto	one
		Wood				PORCH	Fro	ont entry
WALL MATERIA WALL MATERIA		WOOU				WINDOW MATERIA	L	Wood
WALL MATERIA		Wood				WINDOW MATERIA	L	Aluminum
	-	WOOd				WINDOW TYPE		double hung
WALL MATERIA	L 2 (original)					WINDOW CONFIG		1/1; 5/1
		h overhanging ea historic 1/1 wood			. W. е	elevation w/ square batte	erec	d wood columns; 3-sided
								added to west elevation;

ition (not historic); 1 story rear addition; replacement base and wrought iron railings to north entry

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT	2
BUILDER	
ARCHITECT SOURCE	,
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southeast corner of Benton and Sleight (facing Sleight); front and north sidewalks; rear alley; rear picket fence





COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
510 E BEN	TON

DIGITAL	\In
PHOTO ID	10
DIGITAL	\In
PHOTO ID2	10

)	\Images\benton5 10e.jpg	DIGITAL PHOTO ID3
02	\Images\benton5 10e(2).jpg	DIGITAL PHOTOID4

\Image 3).jpg	es\benton510e(
\Image 4).jpg	es\benton510e(

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY

STREET #	530			
DIRECTION	E			
STREET	BENTON			NUL PROFESSION
SUFFIX	AV	Add at a		
PIN	0818317008	A Strat	and the second	
LOCAL SIGNIFICANCE RATING	[C			
POTENTIAL IND NR? (Y or N)	Ν			
Contributing to a NR DISTRICT?	С		Para Maria	
Contributing secon	dary structure? NC	and the second s		
Listed on existing SURVEY?	Local District; NR District			
		GENERAL INFORM	MATION	
CATEGORY bu	uilding	CURRENT FUNCTION	Domestic - single dwel	ling
CONDITION e>	cellent	HISTORIC FUNCTION	Domestic - single dwel	ling
INTEGRITY m	ajor alterations and addition(s)	REASON for SIGNFICANCE		
SECONDARY STRUCTURE	Detached garage			
ARCHITECTURAL DESCRIPTION				
ARCHITECTURA CLASSIFICATION			PLAN	rectangular
DETAILS			NO OF STORIES	2
BEGINYEAR	c. 1925		ROOF TYPE	Side jerkinhead
OTHER YEAR	0. 1929		ROOF MATERIAL	Asphalt - shingle
UTHER TEAK			FOUNDATION	concrete

			FOUNDATION	concrete
DATESOURCE Surveyor			PORCH	Front entry
WALL MATERIA	L (current)	Brick		
WALL MATERIA	L 2 (current)	Stucco	WINDOW MATERIAI	L Wood
	× /		WINDOW MATERIAI	L Aluminum Clad
WALL MATERIAL (original)		Brick	WINDOW TYPE	double hung/casement
WALL MATERIAL 2 (original)		Stucco		double hung/casement
			WINDOW CONFIG	6/1; 10/10; 4-light; 1-light
	Side jerkinhead roof with long shed north and south dormers; center entry with sidelights; front gable entry porch with rounded columns; east side sun porch with casement windows; historic 6/1 and 10/10 double hung windows			
ALTERATIONS	S 2nd story west side addition (originally 1 story garage baynot historic); 1 story west sun porch and covered patio		porch and covered patio	

additions (not historic)

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
v	Southwest corner of Benton and Wright; front and east sidewalk; west alley; similar setbacks; mature trees



COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
530 E BEN	TON

DIGITAL	\Images\b
PHOTO ID	30e.jpg
DIGITAL	\Images\b
PHOTO ID2	30e(2).jpg

\Images\benton5	DIGITAL
30e.jpg	PHOTO ID3
\Images\benton5	DIGITAL
30e(2).jpg	PHOTOID4

\Images\benton530e 3).jpg)(
\Images\benton530e 4).jpg	¥(

STREET #	615				
DIRECTION	E		Contest of the second s		
STREET	BENTON		Mar Contraction of the second	r	
SUFFIX	AV			24	
PIN	0818312005				
LOCAL SIGNIFICANCE RATING	C				
POTENTIAL IND NR? (Y or N)	Ν				
Contributing to a NR DISTRICT?					
Contributing second	lary structure? C				
Listed on existing SURVEY?	Local District; NR District	and all the second		and the second second	
		GENERAL INFO	RMATION		
CATEGORY bu	ilding	CURRENT FUNCTIO	Domestic - single dwel	ling	
CONDITION go	od	HISTORIC FUNCTIO	Domestic - single dwel	ling	
INTEGRITY M	nor alterations	REASON for			
SECONDARY STRUCTURE					
		ARCHITECTURAL	DESCRIPTION		
ARCHITECTURA CLASSIFICATION			PLAN	rectangular	
			NO OF STORIES	1.5	
DETAILS	- 4005		ROOF TYPE	Hipped	
BEGINYEAR	c. 1925		ROOF MATERIAL	Asphalt - shingle	
OTHER YEAR			FOUNDATION	Concrete	
DATESOURCE	Surveyor		PORCH	Front entry enclosed	
WALL MATERIA			WINDOW MATERIA	AL Wood	
WALL MATERIA			WINDOW MATERIA		
WALL MATERIA			WINDOW TYPE	Double hung/awning	
WALL MATERIA	2 2 (original)		WINDOW CONFIG	1/1; 1-light	
SIGNIFICANT FEATURES	lipped roof with overhanging e	aves and exposed rafter tails	; front hipped dormer windo	ow; historic 1/1 wood windows	
ALTERATIONS	nset corner entry porch enclos	ed (historic); 1 story east side	e addition (historic)		

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT	2
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on north side of residential street; front sidewalk; east alley; similar setbacks; mature trees



COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
615 E BEN	TON

DIGITAL	∖lmag
PHOTO ID	15e.jp
DIGITAL	\lmag
PHOTO ID2	15e(2

)	\Images\benton6 15e.jpg	DIGITAL PHOTO ID3
02	\Images\benton6 15e(2).jpg	DIGITAL PHOTOID4

\Images\benton615e(3).jpg
\Images\benton615e(4).jpg

STREET #	620		14.			
DIRECTION	E		le it	Bill W ANV.		
STREET	BENTON					*
SUFFIX	AV		1	ELEN VII	i de la companya de l	ALL
PIN	0818407001			EN PUI		
LOCAL SIGNIFICANCE RATING	С			No NE		
POTENTIAL IND NR? (Y or N)	N					
Contributing to a NR DISTRICT?	С			E	-	
Contributing second	ndary structure	? C				
Listed on existing SURVEY?	Local District;	NR District	-		- alter	
			(GENERAL INFO	DRMATION	
CATEGORY b	uilding			CURRENT FUNCTION	ON Domestic - single dwel	ling
CONDITION	ood			HISTORIC FUNCTI	ON Domestic - single dwel	ling
INTEGRITY	ninor alterations	3		REASON for SIGNFICANCE		
SECONDARY						
STRUCTURE	Detached gar	rage				
	Ť		AR	CHITECTURA	L DESCRIPTION	
ARCHITECTURA CLASSIFICATIO		1			PLAN	irregular
DETAILS					NO OF STORIES	1
BEGINYEAR	c. 1920				ROOF TYPE	Hipped
OTHER YEAR					ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor				FOUNDATION	Not visible
WALL MATERIA		Wood			PORCH	Front enclosed
WALL MATERIA					WINDOW MATERIA	L Wood
WALL MATERIA		Wood			WINDOW MATERIA	
WALL MATERIA	-				WINDOW TYPE	double hung/casement
	× • · · /	L			WINDOW CONFIG	1/1; 8-light
SIGNIFICANT FEATURES	Hipped roof wit historic 1/1 woo		ives; h	hipped porch structure	e (enclosed) w/ square wood	columns on solid knee walls;
ALTERATIONS	Porch enclosed	d w/ 8-light casem	ient wi	indows (historic)		

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	2
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on south side of residential street; front sidewalk; west side alley; similar setbacks; mature trees; patio west of house



COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/30/2007
SURVEYAREA	NAPERVILLE
620 E BEN	TON

DIGITAL	\lr
PHOTO ID	20
DIGITAL	\lr
PHOTO ID2	20

)	\Images\benton6 20e.jpg	DIGITAL PHOTO ID3	
02	\Images\benton6 20e(2).jpg	DIGITAL PHOTOID4	

\Image 3).jpg	s\benton620e(
\Image 4).jpg	s\benton620e(