

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

|                     |                                                |                         |                                                                                                                                         |
|---------------------|------------------------------------------------|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|
| CATEGORY            | <input type="text" value="building"/>          | CURRENT FUNCTION        | <input type="text" value="Education - college"/>                                                                                        |
| CONDITION           | <input type="text" value="excellent"/>         | HISTORIC FUNCTION       | <input type="text" value="Education - college"/>                                                                                        |
| INTEGRITY           | <input type="text" value="minor alterations"/> | REASON for SIGNIFICANCE | <input type="text" value="Despite window alterations, this English Gothic dormitory remains a significant structure in the district."/> |
| SECONDARY STRUCTURE | <input type="text"/>                           |                         |                                                                                                                                         |

**ARCHITECTURAL DESCRIPTION**

|                              |                                                                                                                                                                                                                        |                 |                                                |
|------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|------------------------------------------------|
| ARCHITECTURAL CLASSIFICATION | <input type="text" value="Gothic Revival"/>                                                                                                                                                                            | PLAN            | <input type="text" value="L"/>                 |
| DETAILS                      | <input type="text" value="English"/>                                                                                                                                                                                   | NO OF STORIES   | <input type="text" value="2.5"/>               |
| BEGINYEAR                    | <input type="text" value="1928"/>                                                                                                                                                                                      | ROOF TYPE       | <input type="text" value="Multiple gable"/>    |
| OTHER YEAR                   | <input type="text"/>                                                                                                                                                                                                   | ROOF MATERIAL   | <input type="text" value="Asphalt - shingle"/> |
| DATESOURCE                   | <input type="text" value="NCC"/>                                                                                                                                                                                       | FOUNDATION      | <input type="text" value="Concrete"/>          |
| WALL MATERIAL (current)      | <input type="text" value="Brick"/>                                                                                                                                                                                     | PORCH           | <input type="text" value="-"/>                 |
| WALL MATERIAL 2 (current)    | <input type="text"/>                                                                                                                                                                                                   | WINDOW MATERIAL | <input type="text" value="Vinyl"/>             |
| WALL MATERIAL (original)     | <input type="text" value="Brick"/>                                                                                                                                                                                     | WINDOW MATERIAL | <input type="text"/>                           |
| WALL MATERIAL 2 (original)   | <input type="text"/>                                                                                                                                                                                                   | WINDOW TYPE     | <input type="text" value="double hung/fixe"/>  |
| SIGNIFICANT FEATURES         | <input type="text" value="L-shaped massing; south and west gables and gable parapet walls; shed dormers; stone gothic entries with recessed rounded arches; crenellated parapet walls; stone quoin window surrounds"/> |                 |                                                |
| ALTERATIONS                  | <input type="text" value="replacement windows in original openings (not historic); replacement doors (not historic); glass block replacement windows on north elevation"/>                                             |                 |                                                |

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**

**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME** Grace Evangelical Church/Collins Apts.

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** According to Sanborn Maps, this structure was originally a 1-story church building that was converted to residential between 1909 and 1921.

**PERMITS**

**LANDSCAPE** Southwest corner of Benton and Loomis; front and north sidewalks; rear alley; similar setbacks; mature trees; alternate address--326 E. Benton

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/15/2007

**SURVEYAREA** NAPERVILLE



**DIGITAL PHOTO ID** \Images\loomis005s.jpg

**DIGITAL PHOTO ID3** \Images\loomis005s(3).jpg

**DIGITAL PHOTO ID2** \Images\loomis005s(2).jpg

**DIGITAL PHOTO ID4** \Images\loomis005s(4).jpg

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET #** 8

**STREET** N. LOOMIS ST

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

Aluminum under eaves; wraparound porch (may be extension of historic porch); 2 story rear/N add (not historic); replacement windows in original openings (not historic); replacement door; window on N side of front gable bay looks new; rear deck add. (not historic); side gable N wing extended and roof pitch widened (not historic)

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Northeast corner of Benton and Loomis; front and south sidewalks; rear alley; similar setbacks; mature trees; rear fence

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 15

STREET S. LOOMIS STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Significant Features*

Irregular massing and multiple rooflines; front gable 2 story bay with cornice returns and sunburst motif; northeast 2nd story tower/balcony with conical roof; jerkinhead north side bay; north side pedimented wall dormer; 2 story south 3-sided bay; shingled 2<sup>nd</sup> story; front wraparound porch structure with pedimented front; stained glass transom on front window bay; multi-light windows under gables; half-round window above porch; leaded glass casement windows on 2<sup>nd</sup> story of north elevation



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME** Wickel, William Wallace House

**COMMON NAME**

**COST**

**ARCHITECT** Minott, J. E.

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE** Architectural drawings & specs

**HISTORIC INFO** William Wickel was an early druggist in Naperville. His son in law L. W. Oswald took over Wickel's pharmacy. See continuation sheet.

**PERMITS** Original architectural drawings and specifications for house in address file at Naperville Heritage Society

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; mature trees; large south side yard; parking lot to south

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/15/2007

**SURVEYAREA** NAPERVILLE



**DIGITAL PHOTO ID**

\\images\loomis015s.jpg

**DIGITAL PHOTO ID3**

\\images\loomis015s(3).jpg

**DIGITAL PHOTO ID2**

\\images\loomis015s(2).jpg

**DIGITAL PHOTOID4**

\\images\loomis015s(4).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; large south side lot; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME** Saylor, Jacob House

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/15/2007

**SURVEYAREA** NAPERVILLE



**DIGITAL PHOTO ID** \Images\loomis018s.jpg

**DIGITAL PHOTO ID3** \Images\loomis018s(3).jpg

**DIGITAL PHOTO ID2** \Images\loomis018s(2).jpg

**DIGITAL PHOTO ID4** \Images\loomis018s(4).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Former site of house belonging to E. S. Moyer, treasurer of Kroehler Manufacturing Company, & Walter Givler, cashier at First Nat'l Bank of Naperville. House moved to 400 E. Chicago in 1975.

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/15/2007

**SURVEYAREA** NAPERVILLE

**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear picket fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET #** 24

**STREET** N. LOOMIS STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

Front porch addition (c. 1910); vinyl siding; replacement windows in enlarged, enclosed & downsized openings on front façade, original openings on side elevations (not historic); fixed shutters (not historic); rear 1 story addition; south deck addition (not historic); replacement front door (not historic)

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME** Keiper, Jacob & Sarah House

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Keiper was a Pennsylvania native and book agent. His daughter Lizzie taught at NCC for two years. See continuation sheet.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/14/2007

**SURVEYAREA** NAPERVILLE



**DIGITAL PHOTO ID** \Images\loomis024n.jpg

**DIGITAL PHOTO ID3** \Images\loomis024n(3).jpg

**DIGITAL PHOTO ID2** \Images\loomis024n(2).jpg

**DIGITAL PHOTO ID4** \Images\loomis024n(4).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Franklin and Loomis; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET #** 28

**STREET** S. LOOMIS STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Significant Features*

Hipped main roof with two front gable bays; north and south gabled 2-story bays; 3-sided south 1st story window bay; 1/1 historic wood windows with fluted surrounds, corner bulls eye blocks and classical lintels; polygonal 2 story north side bay with hipped roof



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**

29 N LOOMIS



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET #** 31

**STREET** N. LOOMIS STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Significant Features*

Hipped roof with triangular pedimented front and rear dormers; center front portico w/ triangular pediment; scrolled brackets at cornice; square brick pillars beside massive stone Ionic columns; red brick exterior with buff brick corner quoins and base; front entry with segmental arch above; simple stone label molds over grouped windows; balconet above front entry

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET #** 132

**STREET** S. LOOMIS STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

Original house completely obscured by extensive alterations and additions currently underway—roofline raised and altered; front gable bay extended to south, with new south end porch/entry door; gable at south end of façade is new; north end porch extended; tower north of front gable bay shortened and entry door at base of tower replaced with window; replacement siding (not yet installed); replacement windows in altered openings; front three-sided window bay altered (new windows, new cornice, paneling below); 2-story rear addition



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION

HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**

**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS** 1898 Sanborn shows house with front entry porch; 1909 shows full width front porch.

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear chain link fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/14/2007

**SURVEYAREA** NAPERVILLE



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Van Buren and Loomis; front and north sidewalks; rear driveway; similar setbacks; oversized lot; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear/south side fence

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION

HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**

**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** House acquired by NCC from Wayne & Helen Florey in 1964.

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalks; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/15/2007

**SURVEYAREA** NAPERVILLE



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; large south side yard; rear alley; front sidewalk; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME** Sleight, Delcor House

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; picket fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/15/2007

**SURVEYAREA** NAPERVILLE



**DIGITAL PHOTO ID** \Images\loomis124s.jpg

**DIGITAL PHOTO ID3** \Images\loomis124s(3).jpg

**DIGITAL PHOTO ID2** \Images\loomis124s(2).jpg

**DIGITAL PHOTO ID4** \Images\loomis124s(4).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS** 1909 Sanborn Map (sheet 5) shows building with front and south side entry porches.

**LANDSCAPE** Midblock on east side of residential street; front driveway; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**



STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Sanborn Maps indicate that building may have been late-19th century house that was expanded & altered around 1905.

**PERMITS** Chain of Title in address file at Naperville Heritage Society indicate that the house was built some time between 1873 and 1888.

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear fence; side driveway; large south side yard; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; side driveway; rear chain link fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET #** 140

**STREET** S. LOOMIS STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

Replacement front porch (historic); porch that was recessed in ell of 2 story N side gable bay was enclosed (historic); gable dormer addition (historic); aluminum siding (not historic); front entry addition (historic); 1/1 replacement windows (historic); aluminum awning (not historic); rear porch add.

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS



**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET # 146b  
 DIRECTION N  
 STREET LOOMIS  
 SUFFIX ST  
 PIN  
 LOCAL SIGNIFICANCE RATING C  
 POTENTIAL IND NR? (Y or N) N  
 Contributing to a NR DISTRICT? C  
 Contributing secondary structure? -  
 Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY building CURRENT FUNCTION Domestic - secondary structure  
 CONDITION good HISTORIC FUNCTION Domestic - single dwelling  
 INTEGRITY major alterations and/or addition(s) REASON for SIGNIFICANCE  
 SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION Gable Front PLAN rectangular  
 DETAILS NO OF STORIES 1.5  
 BEGINYEAR c. 1915 ROOF TYPE Front gable  
 OTHER YEAR ROOF MATERIAL Asphalt - shingle  
 DATESOURCE Surveyor FOUNDATION Concrete - block  
 WALL MATERIAL (current) Vinyl PORCH -  
 WALL MATERIAL 2 (current) WINDOW MATERIAL Vinyl  
 WALL MATERIAL (original) Wood WINDOW MATERIAL  
 WALL MATERIAL 2 (original) WINDOW TYPE double hung  
 WINDOW CONFIG 1/1  
 SIGNIFICANT FEATURES Front gable roof and rectangular massing  
 ALTERATIONS Vinyl siding; replacement windows in original openings (not historic); first story window on front façade covered; downsized window on S. side (not historic); replacement front door; fixed shutters (not historic); below grade entry added to N. side

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS** Building first appears as 1.5 story dwelling on Sheet 6 of 1921 Sanborn map.

**LANDSCAPE** Building at rear of lot for 146 N. Loomis; front façade faces alley; no front setback

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/14/2007

**SURVEYAREA** NAPERVILLE

146b N LOOMIS



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET #** 154

**STREET** N. LOOMIS STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

Aluminum siding; fixed shutters (not historic); replacement windows in original openings; 3-part window on front façade 1st story; multi-light wood window linking two first story windows on S. elevation; 2 story rear addition; 3-light & 2/2 windows on N. elevation (historic—1920s); original front entry at north end of front façade converted to window; rear porch addition (1920s)

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of School and Loomis; front and north sidewalks; rear alley; large south side yard; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**