

STREET #	225
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818205001
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	1915	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood - shingle	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	Double & single hung; fixe
		WINDOW CONFIG	1/1;multi/1; 1 & 2-light
SIGNIFICANT FEATURES	Hipped roof with front hipped dormer; full hipped porch with round fluted columns on rusticated concrete block piers/knee wall; shed canopy with curving knee brackets on north side entry; historic 1/1 and leaded glass windows; historic door		
ALTERATIONS	Aluminum siding under eaves and porch; fixed shutters (not historic); south patio addition (not historic); replacement siding (not historic) Roof replacement (admin. approved COA#12-0682)		

HISTORIC INFORMATION

HISTORIC NAME	Attig, Jacob House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	Fry, Oliver
ARCHITECT SOURCE	

HISTORIC INFO	FOR SALE
----------------------	----------

PERMITS	
----------------	--

LANDSCAPE	Southwest corner of Columbia and North; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/5/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------

225 N COLUMBIA



DIGITAL PHOTO ID

\\images\\columbia225n.jpg

DIGITAL PHOTO ID3

\\images\\columbia225n(3).jpg

DIGITAL PHOTO ID2

\\images\\columbia225n(2).jpg

DIGITAL PHOTO ID4

\\images\\columbia225n(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 5

STREET N. COLUMBIA STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

House recently renovated (received Illinois property tax assessment freeze)--large 1.5 story rear addition; replacement siding and shingles; replacement knee brackets and bracing; replacement windows in original openings (window under front gable was probably added when the attic was built out, before the latest renovation); replacement front stoop and entry canopy; north dormer addition

STREET #	5
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818403007
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman Bungalow	PLAN	irregular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	1915	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	-
WALL MATERIAL 2 (current)	Wood - shingle	WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	Double hung/casement/aw
		WINDOW CONFIG	1/1; 1-light; 3-light
SIGNIFICANT FEATURES	Original multi-gabled roof line; historic window openings(except under front gable) on original house; original front entry opening		
ALTERATIONS	House recently renovated--large 1.5 story rear addition; replacement siding and shingles; replacement knee brackets and bracing; replacement windows in original openings--SEE CONTINUATION SHEET		

HISTORIC INFORMATION

HISTORIC NAME	Geiger, C. H. House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	Geiger was president of North Central College from 1946-1960. House was featured in Naperville Heritage Housewalk Brochure. See continuation sheet.
----------------------	---

PERMITS	Certificate of Rehabilitation issued January 2007.
----------------	--

LANDSCAPE	Northwest corner of Columbia and Benton; front and south sidewalks; side driveway; similar setbacks; mature trees; rear wood fence
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/5/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID

\\images\columbia005n.jpg

DIGITAL PHOTO ID3

\\images\columbia005n(3).jpg

DIGITAL PHOTO ID2

\\images\columbia005n(2).jpg

DIGITAL PHOTO ID4

\\images\columbia005n(4).jpg

STREET #	5
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818407002
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Good example of Craftsman style in the district.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman	PLAN	rectangular
DETAILS	Colonial Revival	NO OF STORIES	2.5
BEGINYEAR	1908	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Owner	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood - shingle	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/awning
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Side gable roof with overhanging eaves; full width shed roof front porch with round columns on concrete block piers; front shed dormer; historic 1/1 and 1-light wood windows		
ALTERATIONS	Replacement siding; one story rear addition (may have originally been porch that was enclosed) In kind window & siding replacement (admin. approved COA#13-36) In kind replacement of asphalt shingles (admin. approved COA#17-1941) in kind replacement of porch columns (admin. approved COA#19-1373)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Southwest corner of Columbia and
Benton; front and north sidewalks;
side driveway; similar setbacks;
mature trees; rear picket fence

COA DATE

**COA
DECISION**

PREPARER

Lara Ramsey

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

11/5/2007

SURVEYAREA

NAPERVILLE

5 S COLUMBIA



**DIGITAL
PHOTO ID**

\\images\\columbi
a005s.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia005
s(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a005s(2).jpg

**DIGITAL
PHOTOID4**

\\images\\columbia005
s(4).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="good"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations"/>	REASON for SIGNIFICANCE	<input type="text" value="Excellent, nearly unaltered example of a 1920s brick bungalow."/>
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Bungalow"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1.5"/>
BEGINYEAR	<input type="text" value="c. 1925"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="-"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="Double hung/casement/jal"/>
		WINDOW CONFIG	<input type="text" value="6/1; 3/1; 4/1; 8 & 6-light"/>

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Northeast corner of Columbia and Benton; front and south sidewalks; side driveway; similar setbacks; mature trees; front plantings
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/7/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------

6 N COLUMBIA



DIGITAL PHOTO ID \Images\columbia006n.jpg

DIGITAL PHOTO ID2 \Images\columbia006n(2).jpg

DIGITAL PHOTO ID3 \Images\columbia006n(3).jpg

DIGITAL PHOTO ID4 \Images\columbia006n(4).jpg

STREET #	8
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818408001
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Despite alterations, this remains a great 1860s example of the Greek Revival style.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Greek Revival	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1865	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Brick
WALL MATERIAL (current)	Wood	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Vinyl
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed/awning
		WINDOW CONFIG	6/6; 1-light
SIGNIFICANT FEATURES	Front gable with cornice returns; historic 6/6 wood windows; front gable entry porch roof with cornice returns; multi-light sidelights and transom at entry; classical lintels on windows		
ALTERATIONS	One story north sun porch addition (not historic); fixed shutters; replacement columns and base on porch (not historic); first story window bay addition (south side, historic); two story rear addition; replacement brick foundation Replace escape window (admin. approved COA#11-4104)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Southeast corner of Benton and Columbia; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/6/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------

8 S COLUMBIA



DIGITAL PHOTO ID

\\images\\columbia008s.jpg

DIGITAL PHOTO ID3

\\images\\columbia008s(3).jpg

DIGITAL PHOTO ID2

\\images\\columbia008s(2).jpg

DIGITAL PHOTO ID4

\\images\\columbia008s(4).jpg

STREET #	9
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818407003
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	Typical example of the American Foursquare type in the district.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1910	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor/Title Research	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/fixed/sliding
		WINDOW CONFIG	1/1; 1-light; 1-1
SIGNIFICANT FEATURES	Hipped roof with front and side hipped dormers; full front porch with round columns and square railings; historic 1/1 and 1-light windows		
ALTERATIONS	Replacement dormer windows (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	Sohl, Lawrence House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	Chain of title for property (from Naperville Heritage Society Address Files) indicates house was built between 1905 & 1916. See continuation sheet.
----------------	---

LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/5/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID \\Images\columbia009s.jpg

DIGITAL PHOTO ID2 \\Images\columbia009s(2).jpg

DIGITAL PHOTO ID3 \\Images\columbia009s(3).jpg

DIGITAL PHOTO ID4 \\Images\columbia009s(4).jpg

STREET #	11
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818403005
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Mediterranean Revival	PLAN	Rectangular
DETAILS		NO OF STORIES	1
BEGINYEAR	c. 1930	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Ceramic Tile
DATESOURCE	Surveyor	FOUNDATION	Brick
WALL MATERIAL (current)	Stucco	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Casement/double hung
		WINDOW CONFIG	1-light; 1/1
SIGNIFICANT FEATURES	Side gable roof with ceramic tile; front patio with flat-roof porch over entry; French doors to south of main entry; south end chimney		
ALTERATIONS	Replacement windows in original openings; raised terrace addition south of front porch; wrought iron railing on porch		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA



**DIGITAL
PHOTO ID**

\\images\\columbi
a011n.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia011
n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a011n(2).jpg

**DIGITAL
PHOTO ID4**

\\images\\columbia011
n(4).jpg

STREET #	12
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818408002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Colonial Revival	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	1923	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Naperville Heritage Society	FOUNDATION	concrete
WALL MATERIAL (current)	Wood	PORCH	Canopy
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	8/8; 6/6; multi-light
SIGNIFICANT FEATURES	Side gable roof with cornice returns; historic 8/8 and 6/6 double hung windows and quarter round windows under side gables		
ALTERATIONS	Wood siding (1952); fixed shutters; 2 story rear addition (historic); rear deck addition; replacement front door & surround (1952); gabled front entry canopy addition (1993)		

HISTORIC INFORMATION

HISTORIC NAME	Schuler, Charles Royal House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	Kiest, Charles
ARCHITECT SOURCE	

HISTORIC INFO According to history of house located in address files at Naperville Heritage Society, Charles Schuler and his wife were Chicago natives. Charles worked as an electrical engineer for Commonwealth Edison.

PERMITS Historic photos of house show that it was originally clad in stucco, with blind round arches above 1st story façade windows and round arch recessed front entry.

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; rear wood picket fence; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER Lara Ramsey

PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS

SURVEYDATE 11/6/2007

SURVEYAREA NAPERVILLE



DIGITAL PHOTO ID

\\images\columbia012s.jpg

DIGITAL PHOTO ID3

\\images\columbia012s(3).jpg

DIGITAL PHOTO ID2

\\images\columbia012s(2).jpg

DIGITAL PHOTO ID4

\\images\columbia012s(4).jpg

STREET #	15
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818403003
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1910	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Parged
WALL MATERIAL (current)	Aluminum	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood/Vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	Double & Single hung/cas
		WINDOW CONFIG	1/1; multi/1; multi-light
SIGNIFICANT FEATURES	Hipped roof with front and south hipped dormers; full hipped front porch with round columns on solid knee wall; historic 1/1 first story windows with leaded glass upper sash; historic multi-light casement windows in front dormer		
ALTERATIONS	Replacement 1/1 double hung windows in original openings (not historic); Aluminum siding; 1 story rear addition; rear enclosed porch addition; fixed shutters; wrought iron railings at steps Addition to front porch style (HPC approved COA#19-487)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear picket fence

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA



**DIGITAL
PHOTO ID**

\\images\\columbi
a015n.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia015
n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a015n(2).jpg

**DIGITAL
PHOTO ID4**

\\images\\columbia015
n(4).jpg

STREET #	15
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818407004
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1910-15	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Front gable roof with cornice returns; north and south gable dormers; full front porch with square columns on solid knee wall; historic 1/1 and 1-light wood windows		
ALTERATIONS	Replacement windows under front gable (not historic); window and door openings appear to have been altered under front porch (not historic)		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE



COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

\\images\columbia015s.jpg

DIGITAL PHOTO ID3

\\images\columbia015s(3).jpg

DIGITAL PHOTO ID2

\\images\columbia015s(2).jpg

DIGITAL PHOTOID4

\\images\columbia015s(4).jpg

STREET #	16
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818404011
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Good example of the style, with minor alterations.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne	PLAN	irregular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1905	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Front
WALL MATERIAL 2 (current)	Wood - shingle	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	Double hung/fixed/caseme
		WINDOW CONFIG	1/1; 1-light; multi-light
SIGNIFICANT FEATURES	North front gable bay with north side gable; front oriel window		
ALTERATIONS	Replacement windows in original openings (historic); front porch addition (historic--later enclosed, w/ replacement front steps); awnings (not historic); 2 story rear addition; rear deck addition (not historic) In kind replacement of roof shingles (admin. approved COA#15-2811)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; partial driveway; rear alley; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/7/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID

\\images\columbia016n.jpg

DIGITAL PHOTO ID3

\\images\columbia016n(3).jpg

DIGITAL PHOTO ID2

\\images\columbia016n(2).jpg

DIGITAL PHOTO ID4

\\images\columbia016n(4).jpg

STREET #	18
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818408003
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Well-preserved example of 1920s Colonial Revival residential architecture, with handsome front entry porch.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Colonial Revival	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1925	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/awning/fixed
		WINDOW CONFIG	8/8; 6/6; 1-light
SIGNIFICANT FEATURES	Side gable roof with cornice returns; center entry; barrel arch front entry porch with grouped round columns; historic double hung windows and quarter round windows; south side sun porch; side lights and fanlight at front entry		
ALTERATIONS	First story replacement window in downsized opening on north elevation (not historic); 1 & 2 story rear additions		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; rear picket fence; similar setbacks; mature trees
-----------	--

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/6/2007
------------	-----------

SURVEYAREA	NAPERVILLE
------------	------------



DIGITAL
PHOTO ID

\\images\columbi
a018s.jpg

DIGITAL
PHOTO ID3

\\images\columbia018
s(3).jpg

DIGITAL
PHOTO ID2

\\images\columbi
a018s(2).jpg

DIGITAL
PHOTOID4

\\images\columbia018
s(4).jpg

STREET #	21
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818407005
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Typical example of American Foursquare type in the district.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1910	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double & Single Hung/fixe
		WINDOW CONFIG	3/1; 4/1; 6/1; 4 & 3-light
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves and front hipped dormer; full front porch with classical columns on concrete block piers; 2nd story 3-sided front window bay; historic wood windows; historic wood front door		
ALTERATIONS	Railing at front steps is replacement (not historic); one-story rear additions and second story addition (not historic) Window replacement (admin. approved COA#10-0148)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on west side of residential
street; front sidewalk; rear alley;
similar setbacks; mature trees

COA DATE

**COA
DECISION**

PREPARER

Lara Ramsey

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

11/5/2007

SURVEYAREA

NAPERVILLE



**DIGITAL
PHOTO ID**

\\images\\columbi
a021s.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia021
s(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a021s(2).jpg

**DIGITAL
PHOTO ID4**

\\images\\columbia021
s(4).jpg

STREET #	22
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818404002
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	Handsome Queen Anne-Free Classic residence with flared, pent gable roof and full width front porch.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	Rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	1910	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Owner	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)	Wood - shingle	WINDOW MATERIAL	Wood/leaded glass
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Glass block
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light; multi-light
SIGNIFICANT FEATURES	Pent front gable roof with flared eaves; full front porch with round columns on wood shingle knee walls; shingled 2nd story & gable walls; oriel square window bay w/ flared hip roof on N. side; historic wood windows; rounded S. oriel bay w/ conical roof		
ALTERATIONS	Front entry bay is a possible addition (historic); 2 story rear addition (1994); replacement windows in dormers and under front gable (not historic); rear/south porch and deck addition (not historic); fixed shutters (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/6/2007
------------	-----------

SURVEYAREA	NAPERVILLE
------------	------------



DIGITAL
PHOTO ID

\\images\\columbia022n.jpg

DIGITAL
PHOTO ID3

\\images\\columbia022n(3).jpg

DIGITAL
PHOTO ID2

\\images\\columbia022n(2).jpg

DIGITAL
PHOTO ID4

\\images\\columbia022n(4).jpg

STREET #	23
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818403008
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Fine example of early 20th-century Queen Anne-Free Classic, with flared, pent gable roof and hipped porch with classical columns.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1905	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Parged
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	Double & single hung/fixed
		WINDOW CONFIG	1/1; multi/1; multi-light
SIGNIFICANT FEATURES	Flared front gable roof with pent enclosure; front hipped porch with flared eaves, wood frieze, and round columns on solid knee walls; north side square oriel bay; historic wood and leaded glass windows; north hipped dormer		
ALTERATIONS	Replacement railings at steps (not historic); two story rear addition; 1 story south/rear addition (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Southwest corner of Franklin and Columbia; front and north sidewalks; rear driveway; similar setbacks; mature trees; rear & south picket fence
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/5/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------

23 N COLUMBIA



DIGITAL PHOTO ID \Images\columbia023n.jpg

DIGITAL PHOTO ID2 \Images\columbia023n(2).jpg

DIGITAL PHOTO ID3 \Images\columbia023n(3).jpg

DIGITAL PHOTO ID4 \Images\columbia023n(4).jpg

STREET #	24
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818408004
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front Cottage	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1900	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	-
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	4/4; 8/8; 1/1; 3/1
SIGNIFICANT FEATURES	Front gable roof with lower side gable; 3-sided front window bay; historic double hung windows and front casement window by front entry		
ALTERATIONS	Second story rear addition; classical entry surround with broken pediment (post-1943 alteration--may have occurred when front porch was removed); square south window bay may be historic addition (3/1 wood windows--c. 1925)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	1926 and 1943 Sanborn Maps (sheets 7 and 12) show full width front porch on house.
----------------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; rear chain link fence; similar setbacks; mature trees
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/6/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID \Images\columbia024s(3).jpg

DIGITAL PHOTO ID3

\Images\columbia024s(3).jpg

DIGITAL PHOTO ID2 \Images\columbia024s(2).jpg

DIGITAL PHOTO ID4

\Images\columbia024s(4).jpg

STREET #	26
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818404001
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	Rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1920	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	concrete
WALL MATERIAL (current)	Brick	PORCH	Full front
WALL MATERIAL 2 (current)	Wood/stucco	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	leaded glass
WALL MATERIAL 2 (original)	Wood/stucco	WINDOW TYPE	double & single hung; fixe
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Hipped roof w/ front & side hipped dormers; brick 1st story; full front hipped roof porch w/ square brick columns on solid knee walls; N. side square window bay; historic wood & leaded glass windows		
ALTERATIONS	Aluminum siding under eaves; brick veneer at 2nd story (may be historic alteration); two and one-story rear additions (not historic); rear deck addition (not historic); fixed shutters (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Southeast corner of Franklin and Columbia; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fencing
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/6/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID

\\images\columbia026n.jpg

DIGITAL PHOTO ID3

\\images\columbia026n(3).jpg

DIGITAL PHOTO ID2

\\images\columbia026n(2).jpg

DIGITAL PHOTO ID4

\\images\columbia026n(4).jpg

STREET #	27
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818407006
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Fine Craftsman Bungalow with distinctive stepped brackets under gables.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman Bungalow	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1925	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	concrete
WALL MATERIAL (current)	Brick	PORCH	Front
WALL MATERIAL 2 (current)	Wood	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	aluminum
WALL MATERIAL 2 (original)	Wood	WINDOW TYPE	double hung
		WINDOW CONFIG	4/1
SIGNIFICANT FEATURES	Side gable roof with stepped brackets; front gable dormer with stepped brackets and exposed rafter tails; front gable porch; 1 story south sun porch; historic 4/1 wood windows		
ALTERATIONS	Front porch screened; new steps to front porch (not historic); rear addition to south sun porch; replacement windows in dormer (not historic); one story rear addition		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID2

DIGITAL PHOTO ID3

DIGITAL PHOTO ID4

STREET #	31
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818407007
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	Rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Brick	PORCH	Full front
WALL MATERIAL 2 (current)	Wood	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Aluminum/leaded glass
WALL MATERIAL 2 (original)	Wood	WINDOW TYPE	Double hung/fixed/caseme
		WINDOW CONFIG	3/1; 1/1; 4-light; 10-light
SIGNIFICANT FEATURES	Flared hipped roof with overhanging eaves; front hipped dormer with scrolled brackets; front porch with brick columns and knee walls (appears that south end of porch is historic sun porch); historic 3/1 wood windows; square south side window bay		
ALTERATIONS	North end of porch enclosed w/ multi-light windows and door (not historic); replacement dormer window (not historic); replacement windows on south side bay (not historic) Roof replacement (admin. approved COA#09-2589)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Northwest corner of Columbia and Van Buren; front and south sidewalks; rear driveway; similar setbacks; mature trees
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/5/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID	\Images\columbia031a031s.jpg	DIGITAL PHOTO ID3	\Images\columbia031s(3).jpg
DIGITAL PHOTO ID2	\Images\columbia031s(2).jpg	DIGITAL PHOTO ID4	\Images\columbia031s(4).jpg

STREET #	32
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818408005
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Excellent example of an early 20th century Queen Anne-Free Classic residence, with polygonal corner turret and Ionic columns on porch.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light; multi-light
SIGNIFICANT FEATURES	Front gable with cornice returns; 2nd story polygonal corner bay with conical roof; full front porch w/ round Ionic columns; historic 1/1 and leaded glass windows; 3-sided 1st story S. window bay; hipped N. side dormer		
ALTERATIONS	Solid porch railing on front of porch, missing railings on sides (not historic); replacement windows in dormer and under gable (not historic); rear deck addition (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO Map of Sears-Roebuck Kit home locations in NHS file (called "Sears Homes") indicates that this is a kit home. More research needed to verify this.

PERMITS

LANDSCAPE Northeast corner of Columbia and Van Buren; front and south sidewalks; rear alley; large north side yard; mature trees

COA DATE

COA DECISION

PREPARER Lara Ramsey

PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS

SURVEYDATE 11/6/2007

SURVEYAREA NAPERVILLE



DIGITAL PHOTO ID \Images\columbia032s.jpg

DIGITAL PHOTO ID2 \Images\columbia032s(2).jpg

DIGITAL PHOTO ID3 \Images\columbia032s(3).jpg

DIGITAL PHOTO ID4 \Images\columbia032s(4).jpg

STREET #	105
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818409010
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	Well-preserved example of the Craftsman style, with broad overhanging eaves and decorative L-brackets.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman	PLAN	irregular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1925	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Not visible
WALL MATERIAL (current)	Brick	PORCH	Front deck
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Casement/double hung
		WINDOW CONFIG	9-light; 6/6
SIGNIFICANT FEATURES	Recessed 2nd story; multi-gable roof with overhanging eaves, knee brackets, and exposed rafter tails; historic multi-pane front door with sidelights; broad south wall chimney; historic 6-light and 6/6 wood windows; N. entry porch; battered brick chimney		
ALTERATIONS	wrought iron railings on front patio		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Southwest corner of Columbia and
Van Buren; front and north
sidewalks; rear driveway; similar
setbacks; mature trees

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

105 S COLUMBIA



**DIGITAL
PHOTO ID**

\\images\\columbi
a105s.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia105
s(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a105s(2).jpg

**DIGITAL
PHOTOID4**

\\images\\columbia105
s(4).jpg

STREET #	106
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400011
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	An intact example of the style, with an appropriately-placed rear addition.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1905	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)	Wood - shingle	WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	leaded glass
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	double hung/casement/fixe
		WINDOW CONFIG	1/1; multi-light
SIGNIFICANT FEATURES	Flared hipped roof with overhanging eaves; front & side hipped dormers; full front porch with hipped roof, rounded columns & square railings; wood shingle 2nd story (slight flare at 2nd story break); historic wood windows; 3-sided, 2-story south bay		
ALTERATIONS	Replacement front steps (not historic); large 2 story rear addition, with 2nd south bay and rear porch (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	<input type="text"/>
COMMON NAME	<input type="text"/>
COST	<input type="text"/>
ARCHITECT	<input type="text"/>
ARCHITECT2	<input type="text"/>
BUILDER	<input type="text"/>
ARCHITECT SOURCE	<input type="text"/>

HISTORIC INFO	<input type="text"/>
----------------------	----------------------

PERMITS	1926 Sanborn Map shows building without rear addition.
----------------	--

LANDSCAPE	Northeast corner of Columbia and Franklin; front and south sidewalks; rear alley; rear wood fence; similar setbacks; mature trees
------------------	---

COA DATE	<input type="text"/>
-----------------	----------------------

COA DECISION	<input type="text"/>
---------------------	----------------------

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/6/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------

106 N COLUMBIA



DIGITAL PHOTO ID \Images\columbia106n.jpg

DIGITAL PHOTO ID2 \Images\columbia106n(2).jpg

DIGITAL PHOTO ID3 \Images\columbia106n(3).jpg

DIGITAL PHOTO ID4 \Images\columbia106n(4).jpg

STREET #	106
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818410011
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Bungalow	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	1935	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Owner	FOUNDATION	concrete
WALL MATERIAL (current)	Brick	PORCH	Full front
WALL MATERIAL 2 (current)	Wood	WINDOW MATERIAL	wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Vinyl
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	6/6; 3/1; 1-light
SIGNIFICANT FEATURES	Front gable with cornice returns; hipped front porch with square brick columns on brick knee walls; historic 3/1 and 6/6 wood windows		
ALTERATIONS	South side dormer addition (not historic); replacement 2nd story windows; Aluminum under eaves Steps repair (admin. approved COA#09-3056)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Southeast corner of Columbia and
Van Buren; front sidewalk; rear
driveway; similar setbacks; mature
trees

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

106

S

COLUMBIA



**DIGITAL
PHOTO ID**

\\images\\columbi
a106s.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia106
s(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a106s(2).jpg

**DIGITAL
PHOTO ID4**

\\images\\columbia106
s(4).jpg

STREET #	112
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400010
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Notable example of the Bungalow type, with few alterations.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Bungalow	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1910	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	wood/leaded glass
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Aluminum clad
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/casement/fix
		WINDOW CONFIG	3/1; 6/6; 6/1; 1/1; 9-light
SIGNIFICANT FEATURES	Broad side gable roof with large front gable dormer; full width inset front porch with square columns and railings; historic 6/6, 1/1, 6/1, 3/1 & leaded glass windows on first story		
ALTERATIONS	2 story rear addition (not historic); replacement windows in original openings on 2nd story (not historic)		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fence

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA

112 N COLUMBIA



DIGITAL PHOTO ID

DIGITAL PHOTO ID2

DIGITAL PHOTO ID3

DIGITAL PHOTO ID4

STREET #	114
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818410010
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Typical, early example of the American Foursquare type in the district.
SECONDARY STRUCTURE	Detached garage D. garage (C)		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1905	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Stucco
WALL MATERIAL (current)	Aluminum	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light; multi-light
SIGNIFICANT FEATURES	Steeply pitched flared hipped roof with front hipped dormer; hipped (flared) front porch with round columns on solid knee wall; historic wood and leaded glass windows		
ALTERATIONS	Two story rear addition (historic); 1 story north side addition (not historic); Aluminum siding Demolition of existing front porch & construction of new wrap around porch on the west and south facades of home (HPC approved COA#13-2992)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on east side of residential street; large north side yard; front sidewalk; rear alley; mature trees

COA DATE

**COA
DECISION**

PREPARER

Lara Ramsey

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

11/5/2007

SURVEYAREA

NAPERVILLE



**DIGITAL
PHOTO ID**

\\images\\columbi
a114s.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia114
s(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a114s(2).jpg

**DIGITAL
PHOTO ID4**

\\images\\columbia114
s(4).jpg

STREET #	116
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400009
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	Handsome example of American Foursquare type, with few alterations.
SECONDARY STRUCTURE	Detached garage Shed (C)		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1910	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light; multi-light
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves; front and side hipped dormers; full hipped front porch with round columns on solid knee walls; historic double hung & fixed wood windows; historic front door		
ALTERATIONS	Replacement front steps (not historic); 1 story rear addition		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; house on slight rise, w/ stone retaining wall; rear ally; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/6/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID	\Images\columbia116n(3).jpg	DIGITAL PHOTO ID3	\Images\columbia116n(3).jpg
DIGITAL PHOTO ID2	\Images\columbia116n(2).jpg	DIGITAL PHOTO ID4	\Images\columbia116n(4).jpg

STREET #	117
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301013
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	Rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1870	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete block
WALL MATERIAL (current)	Aluminum	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1
SIGNIFICANT FEATURES	Front gable roof; historic 1/1 wood windows; rear/south side 2 story bay		
ALTERATIONS	Front porch (historic); rear/south side entry porch (not historic); Aluminum siding; fixed shutters (not historic); replacement front door (not historic)		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE
Midblock on west side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA

117 N ELLSWORTH



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #	119
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818409008
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Stately Colonial Revival residence with rounded front portico.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Colonial Revival	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1920	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Not visible
WALL MATERIAL (current)	Wood	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	8/8; 6/6; 6-light; 10-light
SIGNIFICANT FEATURES	Side gable roof with cornice returns; center rounded entry portico with Ionic columns; front entry with leaded glass fanlight and sidelights; gabled front dormers; 1 story north sun porch		
ALTERATIONS	Replacement windows in original openings (not historic); one story rear addition to sun porch (not historic)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on west side of residential street; large north side yard; front sidewalk; side driveway; mature trees

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

119 S COLUMBIA



**DIGITAL
PHOTO ID**

\\Images\\columbi
a119s.jpg

**DIGITAL
PHOTO ID3**

\\Images\\columbia119
s(3).jpg

**DIGITAL
PHOTO ID2**

\\Images\\columbi
a119s(2).jpg

**DIGITAL
PHOTOID4**

\\Images\\columbia119
s(4).jpg

STREET #	120
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400008
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	Fine, well-preserved example of American Foursquare, with handsome detailing at the porch and on the front dormer.
SECONDARY STRUCTURE	Detached garage Shed (C)		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1910	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)	Wood - shingle	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	Double & Single hung
		WINDOW CONFIG	1/1; multi/1
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves; corner rafters; hipped front dormer with segmental arch window opening and scrolled brackets; full front porch with shed roof, rounded columns on shingled knee walls; historic wood windows		
ALTERATIONS	Dormer window boarded up Window replacement (admin. approved COA#11-2071) keep south dormer (constructed without COA) with modifications (HPC approved COA#13-1360)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on east side of residential
street; front sidewalk; rear alley;
similar setbacks; mature trees

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

120 N COLUMBIA



**DIGITAL
PHOTO ID**

\\images\\columbi
a120n.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia120
n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a120n(2).jpg

**DIGITAL
PHOTO ID4**

\\images\\columbia120
n(4).jpg

STREET #	124
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818410005
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	not altered	REASON for SIGNIFICANCE	Fine, unaltered example of Craftsman Bungalow with distinctive stepped brackets.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman Bungalow	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1925	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	concrete
WALL MATERIAL (current)	Brick	PORCH	Front
WALL MATERIAL 2 (current)	stucco	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Stucco	WINDOW TYPE	Casement/double hung
		WINDOW CONFIG	9-light; 4-light
SIGNIFICANT FEATURES	Broad side gable roof w/ stepped brackets; front gable stucco dormer w/ stepped brackets; 9-light wood casement windows; historic double hung wood windows; front gable porch w/ square brick columns on solid knee walls; historic wood door		
ALTERATIONS			

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; mature trees; large (double) lot; rear wood fence
-----------	--

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/5/2007
------------	-----------

SURVEYAREA	NAPERVILLE
------------	------------



DIGITAL
PHOTO ID

\\images\columbia124s.jpg

DIGITAL
PHOTO ID3

\\images\columbia124s(3).jpg

DIGITAL
PHOTO ID2

\\images\columbia124s(2).jpg

DIGITAL
PHOTO ID4

\\images\columbia124s(4).jpg

STREET #	126
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400007
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	Rectangular
DETAILS	Queen Anne - Free Classic	NO OF STORIES	2.5
BEGINYEAR	1907	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood/stained glass
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Aluminum clad
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Full front porch with hipped roof and rounded columns; historic 1/1 windows; two stained glass transoms over 1st story single light windows; south full height 3-sided bay with cutaway corners		
ALTERATIONS	Gabled dormer additions (front and north--not historic); gable over south bay filled with windows (not historic); fixed shutters at 2nd story of front façade (not historic); 1 story rear addition (not historic); vinyl under eaves In kind replacement of front porch (admin. approved COA#15-2384)		

HISTORIC INFORMATION

HISTORIC NAME	Vocks, Herman House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; mature trees; similar setbacks
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/6/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------

126 N COLUMBIA



DIGITAL PHOTO ID \Images\columbia126n.jpg

DIGITAL PHOTO ID2 \Images\columbia126n(2).jpg

DIGITAL PHOTO ID3 \Images\columbia126n(3).jpg

DIGITAL PHOTO ID4 \Images\columbia126n(4).jpg

STREET #	127
DIRECTION	S
STREET	COLUMBIA
SUFFIX	ST
PIN	0818409004
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Prairie	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stucco
WALL MATERIAL (current)	Stucco	PORCH	Front entry canopy
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/awning
		WINDOW CONFIG	3/1; 6/1; 4-light
SIGNIFICANT FEATURES	Broad hipped roof with overhanging eaves; south side hipped dormer; hipped front entry canopy with large brackets; historic 3/1 wood windows & 4-light awning windows; 1-story south sun porch		
ALTERATIONS	One story rear addition (historic); replacement porch stoop, railings, walls (not historic)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Northwest corner of Columbia and
Chicago; front and south sidewalks;
rear driveway; privacy plantings;
mature trees

COA DATE

**COA
DECISION**

PREPARER

Lara Ramsey

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

11/5/2007

SURVEYAREA

NAPERVILLE

127

S

COLUMBIA



**DIGITAL
PHOTO ID**

\\images\columbi
a127s.jpg

**DIGITAL
PHOTO ID3**

\\images\columbia127
s(3).jpg

**DIGITAL
PHOTO ID2**

\\images\columbi
a127s(2).jpg

**DIGITAL
PHOTO ID4**

\\images\columbia127
s(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 130

STREET N. COLUMBIA STREET

ADDITIONAL PHOTOS OR INFORMATION

Significant Features

Steep front gable bay with north side gable bay; projecting front entry and window bay; classical segmental arch entry canopy with fluted engaged columns; segmental arch leaded glass transom; historic door and sidelights; historic windows; scrolled brackets under eaves; shed canopy over north side entry

STREET #	130
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400006
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Tudor Revival	PLAN	Rectangular
DETAILS	Craftsman	NO OF STORIES	1.5
BEGINYEAR	c. 1925	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	metal
WALL MATERIAL 2 (original)		WINDOW TYPE	Casement/double hung
		WINDOW CONFIG	Multi-light; 6/6
SIGNIFICANT FEATURES	Steep front gable bay with north side gable bay; projecting front entry and window bay; classical segmental arch entry canopy with fluted engaged columns; segmental arch leaded glass transom---SEE CONTINUATION SHEET		
ALTERATIONS	One story rear addition; rear porch addition		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley and side driveway; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/6/2007
------------	-----------

SURVEYAREA	NAPERVILLE
------------	------------

130 N COLUMBIA



DIGITAL
PHOTO ID

\\images\\columbi
a130n.jpg

DIGITAL
PHOTO ID3

\\images\\columbia130
n(3).jpg

DIGITAL
PHOTO ID2

\\images\\columbi
a130n(2).jpg

DIGITAL
PHOTO ID4

\\images\\columbia130
n(4).jpg

STREET #	136
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400005
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	Excellent stucco example of the American Foursquare type with Prairie detailing
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS	Prairie	NO OF STORIES	2.5
BEGINYEAR	c. 1920	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Stucco	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	wood
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	1/1; 1-light; multi-light
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves and front hipped dormer; hipped front porch with square stucco columns on solid knee wall; square south window bay; historic wood windows; front door with sidelights		
ALTERATIONS	glass block replacement windows on 2nd story of north elevation		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/6/2007
------------	-----------

SURVEYAREA	NAPERVILLE
------------	------------

136 N COLUMBIA



DIGITAL
PHOTO ID

\\images\columbi
a136n.jpg

DIGITAL
PHOTO ID3

\\images\columbia136
n(3).jpg

DIGITAL
PHOTO ID2

\\images\columbi
a136n(2).jpg

DIGITAL
PHOTO ID4

\\images\columbia136
n(4).jpg

STREET #	142
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400004
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1910	ROOF TYPE	Jerkinhead
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood/vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; multi-light
SIGNIFICANT FEATURES	Front jerkinhead roof with large cornice returns; north and south jerkinhead gables; full front porch with hipped roof, round columns on solid knee wall; historic 1/1 and leaded glass windows		
ALTERATIONS	Aluminum siding; screen door at front entry; replacement multi-light vinyl windows on north elevation Replacement of aluminum siding with fiber cement siding & replacement of windows with aluminum clad windows (admin. approved COA#16-2362) Change in porch style (HPC approved COA#16-2823)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/6/2007
------------	-----------

SURVEYAREA	NAPERVILLE
------------	------------



DIGITAL
PHOTO ID

\\images\columbia142n.jpg

DIGITAL
PHOTO ID3

\\images\columbia142n(3).jpg

DIGITAL
PHOTO ID2

\\images\columbia142n(2).jpg

DIGITAL
PHOTO ID4

\\images\columbia142n(4).jpg

STREET #	146
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400003
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District



GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	The multiple rounded front window bays are the distinguishing features of this 1910s Craftsman house.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman	PLAN	Rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	
WALL MATERIAL (current)	Stucco	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	Leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 3/1; multi-light
SIGNIFICANT FEATURES	Pent front gable w/ overhanging eaves; rounded 1st & 2nd story front window bays; full front porch w/ shed roof, stucco knee walls, & square wood columns; historic 1/1 & 3/1 wood windows; leaded glass windows left (N) of front door; S. square window bay		
ALTERATIONS	3/1 replacement windows under front gable (not historic); wrought iron railings at front steps; dormer addition on north side Repair damaged roof, soffit & fascia (admin. approved COA#12-2903)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on east side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

146 N COLUMBIA



**DIGITAL
PHOTO ID**

\\images\\columbia146n.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia146n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbia146n(2).jpg

**DIGITAL
PHOTO ID4**

\\images\\columbia146n(4).jpg

STREET #	147
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818309002
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	site	CURRENT FUNCTION	Landscape - park
CONDITION	excellent	HISTORIC FUNCTION	Landscape - park
INTEGRITY		REASON for SIGNIFICANCE	
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Park	PLAN	
DETAILS		NO OF STORIES	
BEGINYEAR	c. 2000	ROOF TYPE	
OTHER YEAR		ROOF MATERIAL	
DATESOURCE	Surveyor	FOUNDATION	
WALL MATERIAL (current)		PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	
WALL MATERIAL (original)		WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	
		WINDOW CONFIG	
SIGNIFICANT FEATURES			
ALTERATIONS			

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

College Park

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Southwest corner of Columbia and School; split rail fence; mature trees; front and north sidewalks; playground equipment

COA DATE

**COA
DECISION**

PREPARER

Lara Ramsey

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

11/6/2007

SURVEYAREA

NAPERVILLE

147 N COLUMBIA

**DIGITAL
PHOTO ID**

\\images\columbia147n.jpg

**DIGITAL
PHOTO ID3**

\\images\columbia147n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\columbia147n(2).jpg

**DIGITAL
PHOTOID4**

\\images\columbia147n(4).jpg

STREET #	150
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	Rectangular
DETAILS	Craftsman	NO OF STORIES	2.5
BEGINYEAR	c. 1910	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Stucco	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	Vinyl
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	Multi/1; multi-light
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves and exposed rafter tails; front gable porch with square wood columns on concrete block piers; front hipped dormer		
ALTERATIONS	Replacement windows in original openings (not historic); replacement front door (not historic); two story rear addition; replacement railing and steps on front porch (not historic) Add railing for front porch steps (admin. approved COA#11-4105)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; rear wood fencing; similar setbacks; mature trees
-----------	--

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/6/2007
------------	-----------

SURVEYAREA	NAPERVILLE
------------	------------

150 N COLUMBIA



DIGITAL PHOTO ID

\\images\columbia150n.jpg

DIGITAL PHOTO ID3

\\images\columbia150n(3).jpg

DIGITAL PHOTO ID2

\\images\columbia150n(2).jpg

DIGITAL PHOTO ID4

\\images\columbia150n(4).jpg

STREET #	154
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818400001
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	Rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1910	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Stucco	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	Multilight/1; multi-light
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves and exposed rafter tails; front hipped dormer; front hipped porch with concrete block piers; historic double hung and fixed/casement windows		
ALTERATIONS	Front porch enclosed (historic alteration) In kind replacement of asphalt shingles (admin. approved COA#17-4813)		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southeast corner of Columbia and School; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA

154 N COLUMBIA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #	205
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818205005
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Bungalow	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1925	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Parged
WALL MATERIAL (current)	Stucco	PORCH	Full front
WALL MATERIAL 2 (current)	Aluminum	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	Vinyl
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Side gable roof with overhanging eaves; inset front porch w/ square columns on solid knee walls (rounded corners at porch openings); historic 3-part front window; 1/1 historic first floor windows		
ALTERATIONS	Enlarged front dormer with Aluminum siding and replacement windows (not historic); replacement 2nd story side windows (not historic); green house window on south elevation (not historic) Demolition of existing staircase, awning & bracket, new building addition including enclosed porch on rear side of home (HPC approved COA#11-1157)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	FOR SALE
----------------------	----------

PERMITS	
----------------	--

LANDSCAPE	Northwest corner of Columbia and School; front and south sidewalks; rear driveway; rear fencing; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/5/2007
-------------------	-----------

SURVEYAREA	NAPERVILLE
-------------------	------------

205 N COLUMBIA



DIGITAL PHOTO ID

\\images\\columbia205n.jpg

DIGITAL PHOTO ID3

\\images\\columbia205n(3).jpg

DIGITAL PHOTO ID2

\\images\\columbia205n(2).jpg

DIGITAL PHOTO ID4

\\images\\columbia205n(4).jpg

STREET #	206
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818209004
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	addition(s)	REASON for SIGNIFICANCE	Notable stucco example of American Foursquare, with broad full-front porch and flared hipped roof.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS	Prairie	NO OF STORIES	2.5
BEGINYEAR	c. 1910	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Parged
WALL MATERIAL (current)	Stucco	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	3/1; 2-light
SIGNIFICANT FEATURES	Broad hipped roof with overhanging eaves; front hipped dormer; full width front porch with hipped roof, square stucco columns on solid knee walls, and curved frieze; historic 3/1 and 2-light wood windows		
ALTERATIONS	1 story rear addition		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

206 N COLUMBIA



**DIGITAL
PHOTO ID**

\\images\\columbi
a206n.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia206
n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a206n(2).jpg

**DIGITAL
PHOTOID4**

\\images\\columbia206
n(4).jpg

STREET #	209
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818205004
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	Good/Fair	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	not altered	REASON for SIGNIFICANCE	A solid, unaltered example of the American Foursquare type.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	Rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1905	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	Double & single hung/case
		WINDOW CONFIG	3/1; multi/1; 3 & 1-light
SIGNIFICANT FEATURES	Hipped roof with front hipped dormer; full front hipped roof porch with round columns on solid knee wall; historic 3/1, leaded glass and 3-light windows; first story south square window bay		
ALTERATIONS			

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees (very wooded lot)

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA

209 N COLUMBIA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #	212
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818209003
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Bungalow (altered)	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1925	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)	Stucco	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Vinyl
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	4/1; 5/1; multi-light
SIGNIFICANT FEATURES	Brick 1st story of house, with brick base for front porch; historic wood windows		
ALTERATIONS	Original house obscured by 2nd story addition; front porch roof may also be replacement		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

212 N COLUMBIA



**DIGITAL
PHOTO ID**

\\images\\columbi
a212n.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia212
n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a212n(2).jpg

**DIGITAL
PHOTOID4**

\\images\\columbia212
n(4).jpg

STREET #	215
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818205003
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Dutch Colonial Revival	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1924	ROOF TYPE	Gambrel
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Owner	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)	Stucco	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	vinyl
WALL MATERIAL 2 (original)	Stucco	WINDOW TYPE	double hung/casement
		WINDOW CONFIG	3/1; 6-light
SIGNIFICANT FEATURES	Side gambrel roof with full-width shed dormer; center entry with 5-light sidelights; pedimented front entry porch with round columns; historic 3/1 wood double hung windows		
ALTERATIONS	Replacement 2nd floor casement windows above front entry (not historic); one story rear addition (1985); 2nd story rear addition (not historic); rear deck (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/5/2007
------------	-----------

SURVEYAREA	NAPERVILLE
------------	------------

215 N COLUMBIA



DIGITAL PHOTO ID
\\images\\columbia215n.jpg

DIGITAL PHOTO ID2
\\images\\columbia215n(2).jpg

DIGITAL PHOTO ID3
\\images\\columbia215n(3).jpg

DIGITAL PHOTO ID4
\\images\\columbia215n(4).jpg

STREET #	218
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818209002
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	The unique hipped dormer on this classically detailed American Foursquare features rounded, shingled walls curving into the single centered window.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS	Colonial Revival	NO OF STORIES	2.5
BEGINYEAR	c. 1905	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; diamond
SIGNIFICANT FEATURES	Flared hipped roof with overhanging eaves; hipped dormer with curving, shingled walls around single window; full width front porch with hipped roof and classical columns on solid knee wall; historic 1/1 wood windows;leaded glass window under porch		
ALTERATIONS	Deck addition on roof of rear 1 story bay (not historic); wrought iron railings at front steps (not historic) Addition of 2 dormers, shutters & brackets, repairs of foundation base & vertical lattice, replacement of stairs & railing system, replace three windows, put in wood siding & asphalt shingles, alteration of front doors (HPC approve COA#18-56)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on east side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

COA DATE

**COA
DECISION**

PREPARER

Lara Ramsey

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

11/6/2007

SURVEYAREA

NAPERVILLE

218 N COLUMBIA



**DIGITAL
PHOTO ID**

\\images\columbi
a218n.jpg

**DIGITAL
PHOTO ID3**

\\images\columbia218
n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\columbi
a218n(2).jpg

**DIGITAL
PHOTOID4**

\\images\columbia218
n(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 219

STREET N. COLUMBIA STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Aluminum siding under eaves; wood shingles under gables and on dormers; stucco cladding; front dormer enlarged with replacement windows; replacement windows in original openings; window bay addition (south); green house window (south); fixed shutters; greenhouse window on south elevation; turned wood columns on porch; two story rear addition

STREET #	219
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818205002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1920	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Parged
WALL MATERIAL (current)	Stucco	PORCH	Full front
WALL MATERIAL 2 (current)	Wood - shingle/Aluminum	WINDOW MATERIAL	aluminum
WALL MATERIAL (original)	Stucco	WINDOW MATERIAL	Wood
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/casement/aw
		WINDOW CONFIG	3/1; 3-light; 1-light
SIGNIFICANT FEATURES	Side gable roof; historic 3/1 wood windows under porch		
ALTERATIONS	Replacement front porch; Aluminum siding under eaves; wood shingles under gables and on dormers; stucco cladding; front dormer enlarged with replacement windows; replacement windows in original openings; window bay addition (south)--SEE CONTINUATION SHEET		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on west side of residential street; rear alley; front sidewalk; rear picket fence; similar setbacks; mature trees
-----------	--

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/5/2007
------------	-----------

SURVEYAREA	NAPERVILLE
------------	------------

219 N COLUMBIA



DIGITAL PHOTO ID

\\images\columbia219n.jpg

DIGITAL PHOTO ID3

\\images\columbia219n(3).jpg

DIGITAL PHOTO ID2

\\images\columbia219n(2).jpg

DIGITAL PHOTO ID4

\\images\columbia219n(4).jpg

STREET #	224
DIRECTION	N
STREET	COLUMBIA
SUFFIX	ST
PIN	0818209011
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Good example of early 20th century Queen Anne-Free Classic.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1910	ROOF TYPE	Combination
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Front (enclosed)
WALL MATERIAL 2 (current)		WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Vinyl/leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; diamond
SIGNIFICANT FEATURES	Flared hipped roof with front and north side gables; front dormer with pent gable; inset front/corner porch (enclosed); historic 1/1 wood windows on 1st story; leaded glass window on front façade, diamond pane window in front dormer		
ALTERATIONS	Replacement windows under gables (not historic); front porch enclosed (not historic); south and north side dormer additions; north side deck addition (not historic)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Southeast corner of Columbia and
North; front and north sidewalks;
rear driveway; similar setbacks;
mature trees

COA DATE

**COA
DECISION**

PREPARER

Lara Ramsey

**PREPARER
ORGANIZATION**

GRANACKI HISTORIC
CONSULTANTS

SURVEYDATE

11/6/2007

SURVEYAREA

NAPERVILLE

224

N

COLUMBIA



**DIGITAL
PHOTO ID**

\\images\\columbi
a224n.jpg

**DIGITAL
PHOTO ID3**

\\images\\columbia224
n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\columbi
a224n(2).jpg

**DIGITAL
PHOTOID4**

\\images\\columbia224
n(4).jpg