STREET #	529				1
DIRECTION	Е				学
STREET	CHICAGO				10
SUFFIX	AV		The second second	A STATE OF THE STA	
PIN	0818322016				
LOCAL SIGNIFICANCE RATING POTENTIAL IND NR? (Y or N)  Contributing to a NR DISTRICT? Contributing secon	NC NC dary structure	? -			
Listed on existing SURVEY?	Local District;	NR District			
			GENERAL INFO	<u>ORMATION</u>	
<b>CATEGORY</b> bu	ıilding		CURRENT FUNCTION	ON Domestic - single dwell	ling
<b>CONDITION</b> ex	cellent		HISTORIC FUNCTION	ON Domestic - single dwell	ling
INTEGRITY major alterations and/or addition(s)  REASON for SIGNFICANCE					
SECONDARY STRUCTURE					
			ARCHITECTURA	L DESCRIPTION	_
ARCHITECTURA CLASSIFICATION		itional (altered)		PLAN	irregular
DETAILS		, ,		NO OF STORIES	2
BEGINYEAR	c. 1900			ROOF TYPE	Combination
OTHER YEAR	c. 2000			ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor			FOUNDATION	Not visible
WALL MATERIA		Wood		PORCH	Wrap around
WALL MATERIA		Wood - shingle		WINDOW MATERIA	AL Aluminum
WALL MATERIA		Wood		WINDOW MATERIA	
WALL MATERIA	_			WINDOW TYPE	Double hung/fixed/caseme
				WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Possible that fr	ont gable bay and	d west side two story three-	sided bay are part of origina	I structure
t		replacement wind		east side addition; 2 story e story west side addition; 2	entry addition and polygonal story east/rear bay addition;

#### HISTORIC INFORMATION

<u>HISTORIC INFORMATION</u>
HISTORIC NAME
COMMON NAME
COST
ARCHITECT
ARCHITECT2
BUILDER
ARCHITECT SOURCE
HISTORIC INFO
PERMITS
LANDSCAPE Northwest corner of Chicago and
Wright; front and east sidewalks; rear driveway; rear picket fence;
similar setbacks; mature trees
COA DATE
COA
DECISION
PREPARER Lara Ramsey
PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS
SURVEYDATE 11/28/2007
SURVEYAREA NAPERVILLE
529 E CHICAGO





DIGITAL PHOTO ID

DIGITAL PHOTO ID2 \Images\chicago 529e.jpg

\Images\chicago 529e(2).jpg DIGITAL PHOTO ID3

DIGITAL PHOTOID4 \Images\chicago529e (3).jpg

\Images\chicago529e (4).jpg

# ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET** # 409

**STREET** E. CHICAGO AVENUE

#### **ADDITIONAL PHOTOS OR INFORMATION**

Historic Information

According to article in *The Naperville Sun* (2/6/1998), the house had been converted to a six-flat before the renovation back to single family in 1998.

STREET #	409				
DIRECTION	E				
STREET	CHICAGO				
SUFFIX	AV		\E=		
PIN	0818321008				
LOCAL SIGNIFICANCE RATING	S				
POTENTIAL IND NR? (Y or N)	N				
Contributing to a NR DISTRICT? Contributing second	C down structure	.9			
Listed on existing					
SURVEY?	Local District	; NR District, N			
			<b>GENERAL INFO</b>	<u>ORMATION</u>	
CATEGORY b	uilding		CURRENT FUNCTION	ON Domestic - single dwe	lling
CONDITION e	xcellent		HISTORIC FUNCTION	ON Domestic - single dwe	lling
INTEGRITY	najor alteration	s and/or addition(s	SIGNFICANCE	this elegant Italianate struc	wrap around porch addition, sture remains architecturally
SECONDARY STRUCTURE	-			significant.	
			ARCHITECTURAL	L DESCRIPTION	
ARCHITECTURA CLASSIFICATIO		1		PLAN	Rectangular
	Italianato			NO OF STORIES	2
DETAILS	4070			ROOF TYPE	Hipped
BEGINYEAR	1876			ROOF MATERIAL	Asphalt - shingle
OTHER YEAR	Dais dan as T	'a a Danahara		FOUNDATION	Stone
DATESOURCE	J	our Brochure		PORCH	Wrap around
WALL MATERIA		Stucco		WINDOW MATERI	AL Aluminum clad
WALL MATERIA				WINDOW MATERI	AL
WALL MATERIA		Brick		WINDOW TYPE	double hung
WALL MATERIA	AL 2 (original)			WINDOW CONFIG	1/1
		th center front peo	diment; historic window ope	nings; segmental arch linte	s with center keystones; two-
	skylights; repla	acement door and	cco cladding; front wrap aro transom; 2 story rear additi t (admin. approval COA#13	on; rear garage addition	ndows in original openings;

HISTO	DRIC INFORMATION
HISTORIC NAME	Reuss, George House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
INFO NAF cont Nap Reu	PERVILLE HOMECOMING. See inuation sheet. According to erville Heritage Society brochure, ss was a banker and clothing ufacturer. See continuation sheet.
PERMITS	
Ch rea	ortheast corner of Loomis and icago; front and west sidewalks; ar driveway; wrought iron fence; ature trees
COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/28/2007
SURVEYAREA	NAPERVILLE





DIGITAL PHOTO ID DIGITAL PHOTO ID2 \Images\chicago 409e.jpg DIGITAL PHOTO ID3

\lmages\chicago dIGITAL 409e(2).jpg PHOTOID4

\Images\chicago409e (3).jpg

\Images\chicago409e (4).jpg

09 E CHICAGO

STREET #	423	No.				
DIRECTION	Е		01			
STREET	CHICAGO					
SUFFIX	AV					
PIN	0818321010					
LOCAL SIGNIFICANCE RATING	PS					
POTENTIAL IND NR? (Y or N)	N					
Contributing to a NR DISTRICT?	С				loi I	
Contributing secon	ndary structure	? C				
Listed on existing SURVEY?	Local District	; NR District				
			GENERAL INFO	<u>ORMATION</u>		
CATEGORY b	uilding		CURRENT FUNCTION	ON Domestic - single dwel	ling	
CONDITION g	jood		ON Domestic - single dwel	Domestic - single dwelling		
INTEGRITY minor alterations REASON for Solid, intact local example of the Prairie style.						
			SIGNFICANCE			
SECONDARY STRUCTURE	Detached gai	rage				
ARCHITECTURA	AL	<u>A</u> J	RCHITECTURA	L DESCRIPTION	De ete a suite a	
CLASSIFICATIO	N Prairie			PLAN No on grapping	Rectangular	
DETAILS				NO OF STORIES	2.5	
BEGINYEAR	c. 1915			ROOF TYPE	Hipped	
OTHER YEAR				ROOF MATERIAL	Asphalt - shingle	
DATESOURCE	Surveyor			FOUNDATION FOUNDATION	Parged	
WALL MATERIA	AL (current)	Stucco		PORCH	Full front enclosed	
WALL MATERIA	AL 2 (current)			WINDOW MATERIA		
WALL MATERIA	AL (original)	Stucco		WINDOW MATERIA	AL	
WALL MATERIA				WINDOW TYPE	double hung/awning	
	,			WINDOW CONFIG	1/1; diamond	
			eaves; front hipped do tory east bay; historic 1		nt windows; hipped full front	
ALTERATIONS	2 story rear/ea	st side addition (not his	storic); Aluminum sidin	g under eaves		

#### HISTORIC INFORMATION

11151	ORIC INFORMATION
HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
st	idblock on north side of residential reet; front sidewalk; west side ley; similar setbacks; mature trees
COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC
SURVEYDATE	11/28/2007
SURVEYAREA	NAPERVILLE
423 E CH	ICAGO





DIGITAL PHOTO ID

DIGITAL PHOTO ID2 \Images\chicago 423e(2).jpg

\Images\chicago 423e.jpg DIGITAL PHOTO ID3

DIGITAL PHOTOID4 \Images\chicago423e (3).jpg

\Images\chicago423e (4).jpg

STREET #	427						
DIRECTION	E		1		1	VI L	
STREET	CHICAGO		7			Wasan .	
SUFFIX	AV		Y				
PIN	0818321016						AND MAN
LOCAL SIGNIFICANCE RATING	S						
POTENTIAL IND NR? (Y or N)	N				T		
Contributing to a NR DISTRICT?	С						
Contributing secon	ndary structure	? -	H				
Listed on existing SURVEY?	Local District	; NR District	20/0				
				GENERAL INFO	ORN	<u>IATION</u>	
CATEGORY b	uilding			CURRENT FUNCTION	ON	Domestic - single dwelli	ng
CONDITION g	ood			HISTORIC FUNCTI	ON	Domestic - single dwelli	ng
INTEGRITY	ninor alterations	and addition(s)		REASON for			s, this picturesque Queen
				SIGNFICANCE	Ann	e residence remains arc	hitecturally significant.
SECONDARY STRUCTURE							
ARCHITECTURA	AL		Al	RCHITECTURA	L D		inno muton
CLASSIFICATIO	N Queen Ai	nne				PLAN No or gropping	irregular
DETAILS							2.5
BEGINYEAR	c. 1890					ROOF TYPE	Combination
OTHER YEAR						ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor					FOUNDATION	Stone Wrap around
WALL MATERIA	AL (current)	Wood				PORCH WINDOW MATERIA	
WALL MATERIA	AL 2 (current)	Wood - shingle				WINDOW MATERIA	
WALL MATERIA	AL (original)	Wood				WINDOW MATERIA	double hung/fixed
WALL MATERIA	AL 2 (original)	Wood - shingle				WINDOW THE WINDOW CONFIG	1/1; 1-light
CICNIEICANT	Hippod roof wi	th 2 stary front go	blo b	ov: polygopal post side	2 2 01	tory gable bay; 2nd story	
SIGNIFICANT FEATURES	пірреа тоог мі	in 2 Story front gai	ible b	ay, polygorial east slut	<i>3</i>	ory gable bay, 2nd Story	mont poten
ALTERATIONS				c); east side deck addi nings (historic); rear ga		screened rear addition a	at northeast corner;

#### HISTORIC INFORMATION

11151	JAIC IN ORWATION
HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
Sle rea	orthwest corner of Chicago and eight; front and east sidewalks; ar driveway; wood picket fence; milar setbacks; mature trees
COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/28/2007
SURVEYAREA	NAPERVILLE
JUNILIAMEA	







DIGITAL PHOTO ID

DIGITAL PHOTO ID2 \Images\chicago 427e.jpg

\Images\chicago 427e(2).jpg DIGITAL PHOTO ID3

DIGITAL PHOTOID4 \Images\chicago427e (3).jpg

\Images\chicago427e (4).jpg

127 E CHICAGO

STREET #	523		> 110				
DIRECTION	E	4			AH III		
STREET	CHICAGO	2					
SUFFIX	AV						
PIN	0818322015						
LOCAL SIGNIFICANCE RATING	S						
POTENTIAL IND NR? (Y or N)	N						
Contributing to a NR DISTRICT? Contributing second Listed on existing SURVEY?		? NC cal District; NR					
		<u></u>	GENERAL INFO	<u>ORMATION</u>			
CATEGORY b	uilding		CURRENT FUNCTI	ON Domestic - single dwell	ling		
CONDITION e				IISTORIC FUNCTION Domestic - single dwelling			
INTEGRITY n							
SECONDARY STRUCTURE	Detached gar	rage	SIGNFICANCE	entry & 2nd story center wir	luow bay.		
	. T	<u>A</u> :	RCHITECTURA:	L DESCRIPTION			
ARCHITECTURA CLASSIFICATIO				PLAN	rectangular		
DETAILS				NO OF STORIES	2.5		
BEGINYEAR	c. 1915			ROOF TYPE	Hipped		
OTHER YEAR	0. 1010			ROOF MATERIAL	Asphalt - shingle		
DATESOURCE	Surveyor			<b>FOUNDATION</b>	Concrete		
WALL MATERIA		Brick		PORCH	Front entry canopy		
WALL MATERIA		Stucco		WINDOW MATERIA	AL Wood		
WALL MATERIA		Brick		WINDOW MATERIA	AL		
WALL MATERIA	_	Stucco		WINDOW TYPE	Double hung/casement/aw		
	\ <b>\ \ \</b>			WINDOW CONFIG	6/1; multi-light		
FEATURES	hipped canopy			rindows; center entry with 9-ld window bay; historic double	light sidelights and wood door; e hung, casement, and		
ALTERATIONS							

HISTORIC INFORMATION
HISTORIC NAME
COMMON NAME
COST
ARCHITECT
ARCHITECT2
BUILDER
ARCHITECT SOURCE
HISTORIC INFO
PERMITS
LANDSCAPE Midblock on north side of residential street; front sidewalks; west alley; rear wood fence; similar setbacks; mature trees
COA DATE
COA DECISION
PREPARER Lara Ramsey
PREPARER GRANACKI HISTORIC CONSULTANTS
SURVEYDATE 11/28/2007
SURVEYAREA NAPERVILLE
523 E CHICAGO





DIGITAL PHOTO ID DIGITAL PHOTO ID2 \Images\chicago 523e.jpg

DIGITAL PHOTO ID3

\Images\chicago 523e(2).jpg DIGITAL PHOTOID4 \Images\chicago523e (3).jpg

\Images\chicago523e (4).jpg