

STREET #	229
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818129007
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	1873	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor/tax records	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	Side
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	2/2 vertical
SIGNIFICANT FEATURES	Front gable roof and rectangular massing; 2/2 vertical wood windows (lintels covered with aluminum, but are historic); frieze board		
ALTERATIONS	Appears that front entry was covered up, & new side entry & porch built (post 1943); 2 story rear add. (historic); south add. (post 1943); exterior stair w/ 2nd story S. window converted to door (not historic); aluminum siding; fixed shutters In kind replacement of asphalt shingles (admin. approved COA#17-4764)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	Tax records research by Naperville Heritage Society indicate that house was probably built around 1873.
PERMITS	Sanborn maps through 1943 show house with entry at front and no side porch.
LANDSCAPE	Southwest corner of Ellsworth and North; front and north sidewalks; south side yard; rear driveway; mature trees

COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/16/2007
SURVEYAREA	NAPERVILLE

229 N ELLSWORTH



DIGITAL PHOTO ID	\\images\\ellsworth229n.jpg	DIGITAL PHOTO ID3	\\images\\ellsworth229n(3).jpg
DIGITAL PHOTO ID2	\\images\\ellsworth229n(2).jpg	DIGITAL PHOTO ID4	\\images\\ellsworth229n(4).jpg

STREET #	230
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132001
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)	Stucco	WINDOW MATERIAL	Wood/vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	beveled glass
WALL MATERIAL 2 (original)	Stucco	WINDOW TYPE	Double hung/casement/fix
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves and front hipped dormer; full front porch with round columns on concrete block piers; 1st story north square window bay w/ beveled glass casement windows; beveled glass windows under porch; 3-sided S. window bay		
ALTERATIONS	1/1 replacement windows in original openings (not historic); replacement railing and added frieze on porch In kind shingle replacement (admin. approved COA#16-4595)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Southeast corner of North and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees
-----------	--

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/15/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------

230 N ELLSWORTH



DIGITAL PHOTO ID
\\images\\ellsworth230n.jpg

DIGITAL PHOTO ID2
\\images\\ellsworth230n(2).jpg

DIGITAL PHOTO ID3
\\images\\ellsworth230n(3).jpg

DIGITAL PHOTO ID4
\\images\\ellsworth230n(4).jpg

STREET #	4-6
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314001
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	IHSS (O); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	good	HISTORIC FUNCTION	Commerce/Trade
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	The only commercial block in the historic district, this 19th-century building still retains much of its historic character.
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Two Part Commercial Block	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1880	ROOF TYPE	Flat
OTHER YEAR		ROOF MATERIAL	Not visible
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Brick	PORCH	-
WALL MATERIAL 2 (current)	Stucco	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Vinyl
WALL MATERIAL 2 (original)	wood shingle	WINDOW TYPE	Storefront/double hung
		WINDOW CONFIG	1-light; 1/1
SIGNIFICANT FEATURES	Dentil cornice; northwest corner entry w/ 2nd story rounded turret with wood shingles; cast iron columns at entry; stone segmental arch label molds on window openings w/ rough stone sills		
ALTERATIONS	Brick painted; original conical roof atop round northwest corner tower removed; display windows and storefront door are replacement, but may be historic; concrete steps and railing; replacement upper windows in original openings		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	Historic photograph of building on p. 37 of NAPERVILLE HOMECOMING (1917).
----------------------	---

PERMITS	
----------------	--

LANDSCAPE	Southeast corner of Ellsworth and Benton; front and north sidewalks; building comes to sidewalk; street parking; attached to building at 8 S. Ellsworth on S side
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/15/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

4-6 S ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth004-8s.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth004-6s(2).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth004-6s.jpg

DIGITAL PHOTO ID4

\\images\\ellsworth004-6s(3).jpg

STREET #	8
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314001
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Rare, early example of the I-House in the district, with only minor alterations.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	I-House	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1870	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Brick	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1
SIGNIFICANT FEATURES	Side gable roof and rectangular massing; segmental arch window openings with stone label molds on front façade and brick lintels on side; with rusticated stone sills		
ALTERATIONS	Aluminum siding under eaves (not historic); painted brick exterior; replacement windows in original openings (historic); front entry door and sidelights (historic); replacement front porch (historic); 1 story rear addition (historic)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on east side of residential street; attached to 4-6 S. Ellsworth on N. side; front sidewalk; rear alley; front planting

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

8 S ELLSWORTH



**DIGITAL
PHOTO ID**

\\images\\ellsworth008s.jpg

**DIGITAL
PHOTO ID3**

\\images\\ellsworth008s(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\ellsworth008s(2).jpg

**DIGITAL
PHOTO ID4**

\\images\\ellsworth008s(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 12

STREET S. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Replacement front porch (historic--c. 1910); Aluminum and vertical wood siding (not historic); replacement windows in original openings (openings may have been altered on 1st story under porch, historic); north end door under porch added, and replacement door at south end entry (may be historic alteration); fixed shutters (not historic); 2 story rear addition with exterior stair (not historic); chimney addition

STREET # 12
 DIRECTION S
 STREET ELLSWORTH
 SUFFIX ST
 PIN 0818314002

LOCAL SIGNIFICANCE RATING C

POTENTIAL IND NR? (Y or N) N

Contributing to a NR DISTRICT? C

Contributing secondary structure? -

Listed on existing SURVEY? Local District; NR District



GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - multiple dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	L-Form	PLAN	L
DETAILS	Greek Revival	NO OF STORIES	2
BEGINYEAR	c. 1865	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Aluminum	PORCH	Full front
WALL MATERIAL 2 (current)	wood - vertical board	WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	6/6; 6/9

SIGNIFICANT FEATURES Two story front gable bay with intersecting south side gable wing; historic replacement front porch

ALTERATIONS Replacement front porch (historic--c. 1910); Aluminum and vertical wood siding; replacement windows in original openings (may have been altered on 1st story under porch); north end door under porch added--SEE CONTINUATION SHEET

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/15/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------

12 S ELLSWORTH



DIGITAL PHOTO ID
\\Images\\ellsworth012s.jpg

DIGITAL PHOTO ID2
\\Images\\ellsworth012s(2).jpg

DIGITAL PHOTO ID3
\\Images\\ellsworth012s(3).jpg

DIGITAL PHOTO ID4
\\Images\\ellsworth012s(4).jpg

STREET #	16
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314003
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	IHSS (O); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - multiple dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Excellent example of Italianate residential architecture in the district. Front porch is historic, and dates from the 1910s.
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Duplex-Italianate	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1870	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	vinyl
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1; 2/2 vert.
SIGNIFICANT FEATURES	Shallow mansard roof; historic 2/2 vertical wood windows on 1st story; label molds on all window openings; wide wood frieze under eaves; historic replacement front porch		
ALTERATIONS	Replacement front porch (historic); vinyl replacement windows in original openings on 2nd story (not historic); 2 story rear addition w/ 2nd story deck (not historic); replacement front doors; fixed shutters; 1 story rear/south addition (historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; large south side yard; mature trees
-----------	--

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/15/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------



DIGITAL PHOTO ID
\\Images\\ellsworth016s.jpg

DIGITAL PHOTO ID2
\\Images\\ellsworth016s(2).jpg

DIGITAL PHOTO ID3
\\Images\\ellsworth016s(3).jpg

DIGITAL PHOTO ID4
\\Images\\ellsworth016s(4).jpg

STREET #	<input type="text" value="20"/>
DIRECTION	<input type="text" value="S"/>
STREET	<input type="text" value="ELLSWORTH"/>
SUFFIX	<input type="text" value="ST"/>
PIN	<input type="text" value="0818314004"/>
LOCAL SIGNIFICANCE RATING	<input type="text" value="NC"/>
POTENTIAL IND NR? (Y or N)	<input type="text" value="N"/>
Contributing to a NR DISTRICT?	<input type="text" value="NC"/>
Contributing secondary structure?	<input type="text"/>
Listed on existing SURVEY?	<input type="text" value="Local District; NR District"/>

GENERAL INFORMATION

CATEGORY	<input type="text" value="site"/>	CURRENT FUNCTION	<input type="text" value="Landscape - unoccupied land"/>
CONDITION	<input type="text"/>	HISTORIC FUNCTION	<input type="text" value="Landscape - unoccupied land"/>
INTEGRITY	<input type="text"/>	REASON for SIGNIFICANCE	<input type="text"/>
SECONDARY STRUCTURE	<input type="text"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Vacant Lot"/>	PLAN	<input type="text"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text"/>
BEGINYEAR	<input type="text"/>	ROOF TYPE	<input type="text"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text"/>
DATESOURCE	<input type="text"/>	FOUNDATION	<input type="text"/>
WALL MATERIAL (current)	<input type="text"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL (original)	<input type="text"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text"/>
		WINDOW CONFIG	<input type="text"/>
SIGNIFICANT FEATURES	<input type="text" value="NO BUILDING---IS THIS A VACANT LOT ON ITS OWN, OR SHOULD IT BE TIED TO 16 OR 22 S. ELLSWORTH?"/>		
ALTERATIONS	<input type="text"/>		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

**DIGITAL
PHOTO ID**

**DIGITAL
PHOTO ID2**

**DIGITAL
PHOTO ID3**

**DIGITAL
PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY	<input type="text" value="building"/>	CURRENT FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
INTEGRITY	<input type="text" value="minor alterations and addition(s)"/>	REASON for SIGNIFICANCE	<input type="text" value="Handsome Italianate with exuberant detailing at windows and entry. Listed on IHSS (P)."/>
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Italianate"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1875"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor/Chain of Title"/>	FOUNDATION	<input type="text" value="Stone/concrete block"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="2/2; 6/6; 1/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	Metz, Adam House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	Chain of title indicates Metz purchased property from Alvin Scott in 1874 for \$440. Inventory of Metz estate date 1878 makes mention of house.
----------------	---

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; rear and side picket fence; large south side yard; mature trees
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/15/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID \\images\ellsworth022s.jpg

DIGITAL PHOTO ID2 \\images\ellsworth022s(2).jpg

DIGITAL PHOTO ID3 \\images\ellsworth022s(3).jpg

DIGITAL PHOTO ID4 \\images\ellsworth022s(4).jpg

STREET #	30
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314006
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Shed		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Greek Revival	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1865	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	3/1; 6/6

SIGNIFICANT FEATURES	Front gable roof with wide wood frieze; half-round louvered vent under gable; historic window openings; 1 story north side bay
----------------------	--

ALTERATIONS	Replacement 3/1 wood windows (in altered openings on 1st story façade--1920s); two story rear addition (c. 1940); two story NE corner addition with 2nd story porch; replacement front porch (historic); single front entry door replaced with two doors Addition of 2 upper story windows, modifications to screen porch to windows (admin. approved COA#15-3111) Demolition of existing construction (HPC approved COA#11-2993) Modifications to site plan and building elevations improved (HPC approved COA#13-3320) Construction of new residence (HPC approved COA#15-314)
-------------	--

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Northeast corner of S. Ellsworth and Van Buren; front and south sidewalks; rear/south picket fence; rear alley; oversize lot; mature trees
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/15/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID

\\images\\ellsworth
h030s.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth030
s(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth
h030s(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth030
s(4).jpg

STREET #	104
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319001
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	Quintessential example of Free Classic Queen Anne from around the turn of the 20th century.
SECONDARY STRUCTURE	Barn		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	irregular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1905	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Hipped main roof; front & south 2-story pent gable bays; full front porch with Ionic columns on wood knee wall; historic 1/1 wood windows		
ALTERATIONS	Fixed front window is replacement (possibly historic); replacement porch steps (not historic); rear deck addition (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Southeast corner of Van Buren and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/15/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID

\\images\\ellsworth104s.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth104s(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth104s(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth104s(4).jpg

City of NAPERVILLE
ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY
CONTINUATION SHEET

STREET # 105

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Replacement front door (not historic); front porch add./replacement S. porch (historic--c. 1905); S side door, surround, & canopy/stoop (not historic); glass block in basement windows (not historic); 6/6 replacement windows on N elevation (historic); aluminum canopy & stoop on N entry (not historic)

Additional Information

[from A GUIDE TO CHICAGO'S HISTORIC SUBURBS, p. 401]

“This clapboard farmhouse, built in 1874, has the massing and details reminiscent of Greek Revival, but with pedimented window heads characteristic of the 1870s date. Added at the turn of the century was the porch with its four, standard, Tuscan columns. The west end of the building has a porch from the same construction campaign and columns selected from the same catalogue, but with slightly different proportions.”

STREET #	105
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301015
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	IHSS (HD); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Fine, simple iteration of the Italianate style within the district.
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	1874	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	full front/side
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	2/2 vert.; 6/6
SIGNIFICANT FEATURES	Front gable roof with wood frieze; historic 2/2 wood windows with pedimented lintels		
ALTERATIONS	Replacement front door (not historic); front porch add./replacement S. porch (historic--c. 1905); S side door, surround, & canopy/stoop (not historic); glass block in basement windows (not historic)--SEE CONTINUATION SHEET Replacement of side entry porch (admin. approved COA#12-3641)		

HISTORIC INFORMATION

HISTORIC NAME	Barr, Samuel house
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	Barr, Samuel
ARCHITECT SOURCE	

HISTORIC INFO	1892 Sanborn Map shows no front porch; 1898 map shows front entry porch. Current porch has no entry/steps
----------------------	---

PERMITS	
----------------	--

LANDSCAPE	Northwest corner of Franklin and Ellsworth; front and south sidewalks; side driveway; similar setbacks; mature trees
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/16/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

105 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth105n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth105n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth105n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth105n(4).jpg

STREET #	110
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Minimal Traditional	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c.1950	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Wood	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1
SIGNIFICANT FEATURES	Side gable roof with front gable bay and dormer; front entry porch (altered)		
ALTERATIONS	Wrought iron railings on front porch (may be original); fixed shutters; Aluminum under eaves		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/15/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------

110 S ELLSWORTH



DIGITAL PHOTO ID
\\images\\ellsworth110s.jpg

DIGITAL PHOTO ID2
\\images\\ellsworth110s(2).jpg

DIGITAL PHOTO ID3
\\images\\ellsworth110s(3).jpg

DIGITAL PHOTO ID4
\\images\\ellsworth110s(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 113

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Aluminum siding (not historic); replacement front door/surround/stoop (not historic); 3-sided front window bay (historic); 2 story south/rear addition with entry; replacement windows in original openings (historic); replacement 2nd story window above entry in downsized opening (not historic); 2 & 1 story rear additions

STREET #	113
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301014
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1900	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	side entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed/caseme
		WINDOW CONFIG	4/4; 1/1; multi/1; 3-light
SIGNIFICANT FEATURES	Front gable with south side gable bay (1st story cutaway corners on south bay); concrete block one-car detached garage		
ALTERATIONS	Aluminum siding (not historic); replacement front door/surround/stoop (not historic); 3-sided front window bay (historic); 2 story south/rear addition with entry; replacement windows in original openings (historic)--SEE CONTINUATION SHEET		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on west side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

113 N ELLSWORTH



**DIGITAL
PHOTO ID**

\\images\\ellswort
h113n.jpg

**DIGITAL
PHOTO ID3**

\\images\\ellsworth113
n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\ellswort
h113n(2).jpg

**DIGITAL
PHOTOID4**

\\images\\ellsworth113
n(4).jpg

STREET #	114
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319003
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	Rectangular
DETAILS	Prairie	NO OF STORIES	2.5
BEGINYEAR	c. 1925	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/casement/aw
		WINDOW CONFIG	4/1; 3-light; 9-light geo.
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves; 1 story front bay w/ 9-light geometric wood windows on south end of facade; historic wood windows		
ALTERATIONS	Aluminum under eaves; front entry porch at north end of front facade enclosed, center entry porch added (post 1943); replacement front steps and railing (not historic); rear deck addition (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees
-----------	--

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/15/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------



DIGITAL
PHOTO ID

\\images\\ellsworth
h114s.jpg

DIGITAL
PHOTO ID3

\\images\\ellsworth114
s(3).jpg

DIGITAL
PHOTO ID2

\\images\\ellsworth
h114s(2).jpg

DIGITAL
PHOTO ID4

\\images\\ellsworth114
s(4).jpg

STREET # 119
 DIRECTION N
 STREET ELLSWORTH
 SUFFIX ST
 PIN 0818301012

LOCAL SIGNIFICANCE RATING S

POTENTIAL IND NR? (Y or N) N

Contributing to a NR DISTRICT? C

Contributing secondary structure? -

Listed on existing SURVEY? Local District; NR District



GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Vacant/Not in Use
CONDITION	Good/fair	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	Despite alterations, this Craftsman house remains an excellent example of the style in the district.
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman	PLAN	Rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Gable on hip
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	1/1; 1-light

SIGNIFICANT FEATURES Hipped roof with offset front gable; overhanging eaves; inset front porch (partially enclosed); w/ cast concrete columns on concrete block piers; 2nd story sun porch w/ rows of casement windows

ALTERATIONS Front porch enclosed on north end; most windows are boarded up; steps to front porch missing
 Replacement of door with window in kind replacement matching existing window (admin. approved COA#18-3335)
 Remove window & replace with door, door existed prior to 2018 (admin. approved COA#19-1196)

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/16/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

119 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth119n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth119n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth119n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth119n(4).jpg

STREET #	120
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319004
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	IHSS (O); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Even with the front porch addition and rear additions, this house remains significant local example of the Queen Anne style.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1880	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Front entry
WALL MATERIAL 2 (current)	wood - shingle	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	Double hung/fixed/caseme
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Front gable bay with cutaway corners; scrolled brackets; hipped 2 story south entry bay with front gable porch (round columns); 2 story south side gable bay (may be early/historic addition); historic 1/1 wood windows		
ALTERATIONS	One story north/rear addition; rear deck addition (not historic); casement & fixed windows appear to be replacement, but may be historic; north chimney addition (not historic); front entry porch addition (not historic) In kind replacement of windows (admin. approved COA#18-1902)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/16/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

120 S ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth120s.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth120s(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth120s(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth120s(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 125

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Additional Information

[from A GUIDE TO CHICAGO'S HISTORIC SUBURBS, p. 401]

“This frame house was built about four years earlier than 105 N. Ellsworth Street (Naperville#4) and is slightly grander. Notice that the pedimented windows are larger, its pedimented window heads are slightly grander, and the porch (which here is original) has brackets above the posts that stand on high podia. On the south end is a flat-fronted projection with its own hipped roof. The porch railing is not original.”

STREET #	125
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301011
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	IHSS (P); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Fine local example of the Italianate style, featuring elegant window surrounds topped with triangular pediments. Listed on IHSS (P).
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1870	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	2/2 vertical
SIGNIFICANT FEATURES	Front gable bay w/ south 2 story side gable wing; wood frieze; historic 2/2 vertical wood windows 2/2 triangular pediment lintels; front porch w/ carved wood supports & brackets; 2 story square south window bay; double entry doors		
ALTERATIONS	Rear 2nd story addition; rear screened porch addition		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear picket fence
-----------	--

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/16/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------

125 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth125n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth125n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth125n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth125n(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 126

STREET S. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Significant Features

Front gable roof with wide wood frieze; south polygonal window bay with segmental arch windows, narrow round arch wood panels, carved brackets, and paneled frieze; 2/2 wood windows with flanged pediment lintels; recessed entry with paneled sides & transoms; historic double wood doors (altered)

STREET #	126
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319005
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	IHSS (O); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	Handsome 1870s Italianate, with many historic features.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1875	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	2/2 vertical
SIGNIFICANT FEATURES	Front gable roof with wide wood frieze; 2/2 wood windows with flanged pediment lintels; recessed entry with paneled sides & transoms; historic double wood doors (altered)---SEE CONTINUATION SHEET		
ALTERATIONS	Solid arched glass panes in front doors were probably originally wood (not historic); replacement front and south/rear porches (historic); concrete front steps with wrought iron railing; 1 story north/rear addition (historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/16/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------



DIGITAL PHOTO ID \Images\ellsworth126s.jpg

DIGITAL PHOTO ID2 \Images\ellsworth126s(2).jpg

DIGITAL PHOTO ID3 \Images\ellsworth126s(3).jpg

DIGITAL PHOTO ID4 \Images\ellsworth126s(4).jpg

STREET #	129
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301010
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	irregular
DETAILS	Italianate	NO OF STORIES	2
BEGINYEAR	c. 1865-1870	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone/concrete
WALL MATERIAL (current)	Wood	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	2/2 vertical; 1/1; multi-lig
SIGNIFICANT FEATURES	Original front gable		
ALTERATIONS	Large 2 story rear addition (not historic); entry bay and porch (not historic); replacement windows in altered openings (not historic); replacement siding; possible new label molds (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	FOR SALE
---------------	----------

PERMITS	
---------	--

LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/16/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------

129 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth129n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth129n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth129n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth129n(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 130

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Paired brackets & dentils appear to be later (may be restoration); replacement windows on 2nd story or original structure (not historic); replacement door & transom (not historic); large 2 story S. side addition w/ corner tower (not historic); replacement porch (not historic--ghost lines on original house indicate that there was a full porch); 2 story rear addition (historic); 1 story north bay addition (not historic); segmental arch window on 2nd story north elevation (not historic); chimney (not historic); rear screened porch addition (not historic)

STREET #	130
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818302012
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	IHSS (HD); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate	PLAN	irregular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1870	ROOF TYPE	Combination
OTHER YEAR		ROOF MATERIAL	Wood - shingle
DATESOURCE	surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Brick	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Wood
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; multi-light
SIGNIFICANT FEATURES	Front gable portion is original house (windows on first story appear historic); round arch window openings w/ center keystones; half round window under gable; round arch front entry		
ALTERATIONS	Paired brackets & dentils appear to be later (may be restoration); replacement windows on 2nd story or original structure; replacement door & transom; large 2 story S. side addition w/ corner tower; replacement porch--SEE CONTINUATION SHEET		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO According to history of the house in Naperville Heritage Society address file, the house was built in 1872.

PERMITS See IHSS photograph for original massing of house. According to A GUIDE TO CHICAGO'S HISTORIC SUBURBS (401), the 2 story rear/south addition was built in 1903.

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; parking lot to south; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER Lara Ramsey

PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS

SURVEYDATE 11/15/2007

SURVEYAREA NAPERVILLE

130 N ELLSWORTH



DIGITAL PHOTO ID

\\images\ellsworth
h130n.jpg

DIGITAL PHOTO ID3

\\images\ellsworth130
n(3).jpg

DIGITAL PHOTO ID2

\\images\ellsworth
h130n(2).jpg

DIGITAL PHOTO ID4

\\images\ellsworth130
n(4).jpg

STREET #	130
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319006
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	not altered	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Minimal Traditional	PLAN	L
DETAILS		NO OF STORIES	1
BEGINYEAR	c. 1950	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Not visible
WALL MATERIAL (current)	Stone veneer	PORCH	Front entry
WALL MATERIAL 2 (current)	Brick	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stone veneer	WINDOW MATERIAL	Glass block
WALL MATERIAL 2 (original)	Brick	WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	2/2; 2/3; multi-light
SIGNIFICANT FEATURES	Stone veneer on façade; hipped roof with overhanging eaves; rounded corner entry; historic double hung & multi-light wood windows; 3-sided front window bay; glass block beside entry		
ALTERATIONS			

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA

130 S ELLSWORTH



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #	133
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301009
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	IHSS (P); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	shed		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Greek Revival	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1860	ROOF TYPE	Front gable
OTHER YEAR	c. 1975	ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor/IHSS	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	
WALL MATERIAL 2 (current)	Stone veneer	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	6/1; 1/1
SIGNIFICANT FEATURES	Front gable roof and rectangular massing		
ALTERATIONS	Aluminum siding (not historic); stone veneer on 1st story façade (not historic); replacement windows (in some original openings on side elevations, historic); 1st story façade clad (see IHSS photo); 1 story rear addition		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fence

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA

133 N ELLSWORTH



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 135

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

According to Sanborn Maps, house was originally a one-story structure that has been altered and added to over the years: 1 story south side addition is historic, but south porch appears to have been altered (replacement posts, railing, and steps, Aluminum under eaves); second story addition to original house is historic; first story on north addition was added before 1943, with 2nd story added after; aluminum siding; replacement windows in altered openings (not historic--house originally had a full porch and entry on front façade); multiple rear additions; stone steps to north side entry and stone patio at front of house (not historic)

STREET #	135
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301008
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1867	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	1/1; 4-light
SIGNIFICANT FEATURES	Gable front portion of original house (first story only is original, with 2nd story an historic addition)		
ALTERATIONS	According to Sanborn Maps, house was originally a one-story structure that has been altered and added to over the years--SEE CONTINUATION SHEET. In kind replacement of front porch (admin. approved COA#16-2613)		

HISTORIC INFORMATION

HISTORIC NAME	Sporlein, Mary Elizabeth House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; low stone wall around lot; similar setbacks; mature trees
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/16/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

135 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth
h135n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth135
n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth
h135n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth135
n(4).jpg

STREET #	136
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818302002
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Good local example of early 20th century Queen Anne.
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne	PLAN	irregular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1905	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Glass block
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; diamond/1
SIGNIFICANT FEATURES	Steep hipped roof with front and side gables; cornice returns; inset corner entry porch (altered); historic 1/1 wood windows; historic diamond-pane windows under front & side gables		
ALTERATIONS	Aluminum siding (not historic); porch has been downsized (see Sanborn maps), with replacement wrought iron supports/railings and concrete steps (not historic); rear porch addition; 2nd story rear addition; glass block in basement windows In kind replacement of windows (admin. approved COA#18-2732)		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS Sanborn maps (1909-1943) show a larger inset corner entry porch. See continuation sheet.

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA

136 N ELLSWORTH



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 142

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Replacement siding (not historic); replacement windows in original openings (not-historic); replacement door (not historic); replacement supports/railing on porch (not historic); 3-sided 1st story south window bay addition (not historic); large 2 story rear/south addition (not historic); rear porch addition (not historic)

STREET #	142
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818302001
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1910	ROOF TYPE	Gable on hip
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Wrap around
WALL MATERIAL 2 (current)	Wood - shingle	WINDOW MATERIAL	Vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	double hung
		WINDOW CONFIG	1/1
SIGNIFICANT FEATURES	Front gable roof; wraparound porch structure (roof); 2 story south side hipped roof bay		
ALTERATIONS	Replacement siding (not historic); replacement windows in original openings (not-historic); replacement door (not historic); replacement supports/railing on porch (not historic)--SEE CONTINUATION SHEET Front steps replacement (admin. approved COA#12-2252)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/15/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------

142 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth142n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth142n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth142n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth142n(4).jpg

STREET #	144
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818133002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Solid example of Gable Front vernacular type.
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1880	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/fixed/single h
		WINDOW CONFIG	1/1; 2-light
SIGNIFICANT FEATURES	Front gable roof; 2 story south side gable bay with 1st story cutaway corners; historic 1/1 double and single hung windows; historic porch roof and columns		
ALTERATIONS	Replacement base on porch (historic); replacement siding (historically appropriate); replacement front door (not historic); 2nd story projecting gable addition on north elevation (not historic); two story rear addition (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/15/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------

144 N ELLSWORTH



DIGITAL PHOTO ID

\\images\ellsworth144n.jpg

DIGITAL PHOTO ID3

\\images\ellsworth144n(3).jpg

DIGITAL PHOTO ID2

\\images\ellsworth144n(2).jpg

DIGITAL PHOTO ID4

\\images\ellsworth144n(4).jpg

STREET #	145
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818130005
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Ranch	PLAN	irregular
DETAILS		NO OF STORIES	1
BEGINYEAR	c. 1950	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Not visible
WALL MATERIAL (current)	Stone veneer	PORCH	Front entry
WALL MATERIAL 2 (current)	Aluminum	WINDOW MATERIAL	Vinyl
WALL MATERIAL (original)	Stone veneer	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Wood	WINDOW TYPE	Casement/fixed
		WINDOW CONFIG	Multi-light; 1-light
SIGNIFICANT FEATURES	Side gable roof with lower front gable bay at north end of front façade; stone veneer cladding; front entry porch		
ALTERATIONS	Aluminum awnings; replacement windows in original openings (not historic); aluminum under gables and eaves In kind shingle replacement in areas where small fire occurred (admin. approved COA#18-4656)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on west side of residential street; front sidewalk; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/16/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

145 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth145n.jpg

DIGITAL PHOTO ID2

\\images\\ellsworth145n(2).jpg

DIGITAL PHOTO ID3

\\images\\ellsworth145n(3).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth145n(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 151

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Recent renovation. Appropriate restoration work includes: replacement siding; replacement porch spindles and supports; replacement 1/1 windows; multi-light replacement windows on front bay; north entry porch; 1 story rear addition. Inappropriate alterations include glass block basement windows and a large 2-story addition to the south, including entry and porch, which is difficult to distinguish from the original massing of the home.

STREET # 151
 DIRECTION N
 STREET ELLSWORTH
 SUFFIX ST
 PIN 0818130004

LOCAL SIGNIFICANCE RATING S

POTENTIAL IND NR? (Y or N) N

Contributing to a NR DISTRICT? C

Contributing secondary structure? C

Listed on existing SURVEY? IHSS (O); Local District; NR



GENERAL INFORMATION

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	Despite alterations, this Queen Anne-style house remains an excellent example of the style within the district.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	1896	ROOF TYPE	Combination
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Front/side
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; multi-light

SIGNIFICANT FEATURES Front bay w/ cutaway corners on 1st story and shingles/sunburst motif under gable; hipped main roof; flush north side gable; 1/1 windows on original house are historic (not original)

ALTERATIONS Recent renovation. Appropriate restoration work includes: replacement siding; replacement porch spindles and supports; replacement 1/1 windows; multi-light replacement windows on front bay; north entry porch--SEE CONTINUATION SHEET

HISTORIC INFORMATION

HISTORIC NAME	Schwartz, Charles
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO See IHSS photograph for appearance of house before renovation. Featured on p. 402 of A GUIDE TO CHICAGO'S HISTORIC SUBURBS.

PERMITS

LANDSCAPE Southwest corner of Ellsworth and School; front and north sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER Lara Ramsey

PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS

SURVEYDATE 11/16/2007

SURVEYAREA NAPERVILLE

151 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth151n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth151n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth151n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth151n(4).jpg

STREET #	152
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818133001
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Despite alterations, this house remains a fine local example of the style.
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne	PLAN	irregular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1900	ROOF TYPE	Gable on hip
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	aluminum clad
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Glass block
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Front gable bay with 1st story cutaway corners; hipped two story north and south (altered) bays; square north window bay; classical wood lintels		
ALTERATIONS	Replacement front porch (appears to be appropriate); replacement windows in original openings (not historic) replacement siding; S. bay extended & S. porch added (not historic); 1 story rear add.; square N window bay add.; north gable window boarded up		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Southeast corner of School and Ellsworth; front and north sidewalks; picket fence; rear driveway; similar setbacks; mature trees
-----------	--

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/15/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------

152 N ELLSWORTH



DIGITAL
PHOTO ID

\\images\ellsworth
h152n.jpg

DIGITAL
PHOTO ID3

\\images\ellsworth152
n(3).jpg

DIGITAL
PHOTO ID2

\\images\ellsworth
h152n(2).jpg

DIGITAL
PHOTO ID4

\\images\ellsworth152
n(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 206

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Aluminum siding; fixed shutters (not historic); original front entry replaced with window (historic); north entry & porch (not historic); replacement 6-light casement windows (historic); 2 story north addition (historic); south side porch extended (historic) & enclosed; 1 story rear addition (historic); rear exterior stair (not historic)

STREET #	206
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132006
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	Good/fair	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	irregular
DETAILS	Italianate	NO OF STORIES	2
BEGINYEAR	c. 1870	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	Side Entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	2/2 vertical; 6-light
SIGNIFICANT FEATURES	Front gable roof; historic 2/2 wood windows; square south two story window bay (early addition); N. side oval window		
ALTERATIONS	Aluminum siding; fixed shutters (not historic); original front entry replaced with window (historic); north entry & porch (not historic); replacement 6-light casement windows (historic)--SEE CONTINUATION SHEET		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Northeast corner of School and
Ellsworth; front and south sidewalks;
rear alley; rear wood fence; large
north side yard

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

206 N ELLSWORTH



**DIGITAL
PHOTO ID**

\\images\\ellswort
h206n.jpg

**DIGITAL
PHOTO ID3**

\\images\\ellsworth206
n(3).jpg

**DIGITAL
PHOTO ID2**

\\images\\ellswort
h206n(2).jpg

**DIGITAL
PHOTO ID4**

\\images\\ellsworth206
n(4).jpg

STREET #	214
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132005
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Rare brick example of this vernacular type.
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	L-Form	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	1869	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Stone
WALL MATERIAL (current)	Brick	PORCH	Front
WALL MATERIAL 2 (current)	aluminum	WINDOW MATERIAL	Vinyl
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/storm
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Two story front gable bay with south side gable wing; segmental arch window openings with soldier course lintels, wide frieze board, concrete block entry porch addition with hipped roof, concrete block piers & knee walls, wood columns		
ALTERATIONS	Brick painted; two story rear addition; replacement porch (later enclosed--historic); replacement windows in slightly downsized openings (not historic); 1 story rear addition; Aluminum frieze (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	Helm, Daniel House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/15/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

214 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth214n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth214n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth214n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth214n(4).jpg

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 215

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Original house obscured by multiple alterations--aluminum siding; 1st story front entry addition (not historic); 2 story rear addition (not historic--abuts historic north side bay with 1st story cutaway corners); 1 story south/rear addition (historic-built between 1926 and 1943); wrought iron over entry; round front window (original front 1st story windows covered up); replacement window on 2nd story of north elevation; south side toward rear covered in stone veneer, wrought iron railing and floor-to-ceiling fixed windows & door on 2nd story of south side (toward rear)

STREET #	215
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818129010
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne (altered)	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1880	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Front gable; south side gable with 1st story cutaway corners; recessed north side 2 story bay w/ 1st story cutaway corners; some historic 1/1 windows on original massing		
ALTERATIONS	Original house obscured by multiple alterations--aluminum siding; 1st story front entry addition (not historic); 2 story rear addition; 1 story south side addition; wrought iron over entry---SEE CONTINUATION SHEET		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
---------------	--

PERMITS	
---------	--

LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
-----------	---

COA DATE	
----------	--

COA DECISION	
--------------	--

PREPARER	Lara Ramsey
----------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
-----------------------	-------------------------------

SURVEYDATE	11/16/2007
------------	------------

SURVEYAREA	NAPERVILLE
------------	------------

215 N ELLSWORTH



DIGITAL PHOTO ID
\\images\\ellsworth215n.jpg

DIGITAL PHOTO ID3
\\images\\ellsworth215n(3).jpg

DIGITAL PHOTO ID2
\\images\\ellsworth215n(2).jpg

DIGITAL PHOTO ID4
\\images\\ellsworth215n(4).jpg

STREET #	219
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818129009
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Aluminum	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Unknown	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement/sto
		WINDOW CONFIG	3/1; 1/1; 4-light; 1-light
SIGNIFICANT FEATURES	Broad front gable roof; front gable porch with brick knee walls (enclosed); historic 3/1 wood windows under gable		
ALTERATIONS	Historic 1/1 and 1-light casement window replacements in original openings; Aluminum siding; rear/south entry and porch addition; 2 story rear addition		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on west side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees
------------------	--

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/16/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

219 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth219n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth219n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth219n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth219n(4).jpg

STREET #	220
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132004
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Bungalow	PLAN	rectangular
DETAILS	Tudor Revival	NO OF STORIES	1.5
BEGINYEAR	c. 1930	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Glass block
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	6/6; 8/8; 6-light
SIGNIFICANT FEATURES	Front gable roof with one story front gable bay; inset front entry porch in bay		
ALTERATIONS	Replacement windows in original openings (not historic); 3-sided window bay addition on south side (not historic)		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	

HISTORIC INFO	
----------------------	--

PERMITS	
----------------	--

LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear fence
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/15/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

220 N ELLSWORTH



DIGITAL PHOTO ID

\\images\\ellsworth220n.jpg

DIGITAL PHOTO ID3

\\images\\ellsworth220n(3).jpg

DIGITAL PHOTO ID2

\\images\\ellsworth220n(2).jpg

DIGITAL PHOTO ID4

\\images\\ellsworth220n(4).jpg

STREET #	223
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818129008
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District; N

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Fine, intact example of early 20th-century combination of the American Foursquare and Queen Anne - Free Classic styles.
SECONDARY STRUCTURE	Carriage house		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS	Queen Anne - Free Classic	NO OF STORIES	2.5
BEGINYEAR	1908	ROOF TYPE	Gable on hip
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 2-light
SIGNIFICANT FEATURES	Gable on hip roof; full front porch with rounded columns; 2 story north 3-sided bay with pent gable roof; north hipped dormer; historic wood cladding		
ALTERATIONS	Replacement 1/1 windows in original openings (not historic--appropriate configuration); 1 story rear addition (1999)		

HISTORIC INFORMATION

HISTORIC NAME	Patterson, William Henry House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	McCorkel, Frank
ARCHITECT SOURCE	

HISTORIC INFO	Patterson, a farmer in Wheatland Township, had the home built after his retirement.
----------------------	---

PERMITS	
----------------	--

LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear driveway; similar setbacks; mature trees; rear wood fencing
------------------	---

COA DATE	
-----------------	--

COA DECISION	
---------------------	--

PREPARER	Lara Ramsey
-----------------	-------------

PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
------------------------------	-------------------------------

SURVEYDATE	11/16/2007
-------------------	------------

SURVEYAREA	NAPERVILLE
-------------------	------------

223 N ELLSWORTH



DIGITAL PHOTO ID \Images\ellsworth223n.jpg

DIGITAL PHOTO ID2 \Images\ellsworth223n(2).jpg

DIGITAL PHOTO ID3 \Images\ellsworth223n(3).jpg

DIGITAL PHOTO ID4 \Images\ellsworth223n(4).jpg

STREET #	224
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132003
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	excellent	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gabled Ell	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1900	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Wrap around
WALL MATERIAL 2 (current)	Wood - shingle	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Vinyl
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	double hung
		WINDOW CONFIG	1/1; 9/9
SIGNIFICANT FEATURES	Two story front gable bay and S. side ell; historic 1/1 wood windows on first story		
ALTERATIONS	Wrap around front porch with new concrete blk piers(not historic); replacement windows in original openings on 2nd story (not historic); replacement siding; stained glass replacement window on north side and under front gable; 1 story rear porch addition		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA

224 N ELLSWORTH



DIGITAL PHOTO ID

DIGITAL PHOTO ID2

DIGITAL PHOTO ID3

DIGITAL PHOTO ID4