City of NAPERVILLE

| STREET# | 218 | | | | |
|--|------------------|-------------|--|--|---|
| DIRECTION | | | | | |
| STREET | NORTH | | | | |
| SUFFIX | AV | | e Walling | | |
| PIN | 0818132013 | | | | |
| LOCAL SIGNIFICANCE RATING | С | | | 215 | |
| POTENTIAL IND NR? (Y or N) | N | | | | |
| Contributing to a NR DISTRICT? | С | | | | |
| Contributing secon | dary structure? | - | The same of the sa | | |
| Listed on existing SURVEY? | Local District; | NR District | | | |
| | | | GENERAL INFO | <u>ORMATION</u> | |
| CATEGORY bu | ilding | | CURRENT FUNCTION | ON Domestic - single dwell | ing |
| CONDITION go | ood | | HISTORIC FUNCTION | ON Domestic - single dwell | ing |
| INTEGRITY m | inor alterations | | REASON for SIGNFICANCE | | |
| SECONDARY STRUCTURE | | | | | |
| | | | <u>'</u> | | |
| ARCHITECTURA | L | | ARCHITECTURAL | | |
| CLASSIFICATION | | nt | | PLAN | Rectangular |
| DETAILS | | | NO OF STORIES 2 | | |
| BEGINYEAR | c. 1900 | | | ROOF TYPE | Front gable |
| OTHER YEAR | | | | ROOF MATERIAL | Asphalt - shingle |
| DATESOURCE Surveyor | | | | FOUNDATION | Stone |
| WALL MATERIA | L (current) | Vinyl | | PORCH | Full front |
| WALL MATERIA | L 2 (current) | | | WINDOW MATERIA | - |
| WALL MATERIA | L (original) | Wood | | WINDOW MATERIA | |
| WALL MATERIAL 2 (original) | | | | WINDOW CONFIC | Double & single hung; cas 1/1; 1-light |
| | | | | g leaded glass and leaded g d columns on concrete block | lass casement (damaged) |
| Replacement siding (not historic); vinyl replacement windows in original openings; fixed shutters; replacement door (not historic); replacement railings and columns on porch (ca. 1910) | | | | | |

HISTORIC INFORMATION

| INSTORIC INFORMATION |
|---|
| HISTORIC NAME |
| COMMON NAME |
| COST |
| ARCHITECT |
| ARCHITECT2 |
| BUILDER |
| ARCHITECT SOURCE |
| HISTORIC INFO |
| |
| PERMITS |
| LANDSCAPE Midblock on south side of residential street; front sidewalk; east side alley; similar setbacks; mature trees |
| |
| COA DATE |
| COA DECISION |
| PREPARER Lara Ramsey |
| PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS |
| SURVEYDATE 11/30/2007 |
| SURVEYAREA NAPERVILLE |
| 218 NORTH |





DIGITAL PHOTO ID

DIGITAL PHOTO ID2 \Images\north21 8(2).jpg

\Images\north21 8.jpg DIGITAL PHOTO ID3

DIGITAL PHOTOID4 \Images\north218(3).j

\Images\north218(4).j

City of NAPERVILLE

| STREET # | 214 | | | | | | |
|---------------------------------|------------------|----------------------|--|--------------------------|---|--|--|
| DIRECTION | | | | | | | |
| STREET | NORTH | | AL DE LA SECTION AND ADDRESS OF THE PARTY OF | | | | |
| SUFFIX | AV | | | | | | |
| PIN | 0818132012 | | | | ### N | | |
| LOCAL SIGNIFICANCE RATING | С | | | | | | |
| POTENTIAL IND NR? (Y or N) | N | | | | | | |
| Contributing to a NR DISTRICT? | С | | | | | | |
| Contributing second | dary structure | ? - | | | 8 _ 6 | | |
| Listed on existing SURVEY? | Local District | ; NR District | and the second second second | | | | |
| | | | GENERAL INFO | <u>ORMATION</u> | _ | | |
| CATEGORY bu | uilding | | CURRENT FUNCTION | ON Domestic - multiple d | welling | | |
| CONDITION fai | ir | | HISTORIC FUNCTI | ON Domestic - single dwe | Domestic - single dwelling | | |
| INTEGRITY ma | ajor alterations | s and/or addition(s) | REASON for SIGNFICANCE | | | | |
| SECONDARY STRUCTURE | | | | | | | |
| | | | ARCHITECTURA | L DESCRIPTION | | | |
| ARCHITECTURAL CLASSIFICATION | | nd Wing | | PLAN | Rectangular | | |
| DETAILS | 1 3 | <u> </u> | | NO OF STORIES | 2 | | |
| BEGINYEAR | c. 1870 | | | ROOF TYPE | Combination | | |
| OTHER YEAR | 0. 1070 | | | ROOF MATERIAL | Asphalt - shingle | | |
| DATESOURCE | Surveyor | | | FOUNDATION | Stone/concrete - block | | |
| WALL MATERIA | _ | Aluminum | | PORCH | Front entry | | |
| WALL MATERIA | | | | WINDOW MATER | IAL Vinyl | | |
| WALL MATERIA | | Wood | | WINDOW MATER | | | |
| WALL MATERIAL 2 (original) | | | | WINDOW TYPE | double hung/fixed | | |
| | , 6 | | | WINDOW CONFIG | 1/1; 1-light | | |
| SIGNIFICANT FEATURES | Front gable ba | y and recessed side | le gable wing (now obscur | ed by later addition) | | | |
| c | | | | | n-historic); replacement front utters; rear porch addition (non- | | |

HISTORIC INFORMATION

| HISTORIC INFORMATION | | | | |
|--------------------------|--|--|--|--|
| HISTORIC NAME | | | | |
| COMMON NAME | | | | |
| COST | | | | |
| ARCHITECT | | | | |
| ARCHITECT2 | | | | |
| BUILDER | | | | |
| ARCHITECT SOURCE | | | | |
| HISTORIC INFO | | | | |
| DEDMING | | | | |
| PERMITS | | | | |
| stre | block on south side of residential et; front sidewalk; side driveway rtial); similar setbacks; mature es | | | |
| COA DATE | | | | |
| COA DECISION | | | | |
| PREPARER | Lara Ramsey | | | |
| PREPARER ORGANIZATION | GRANACKI HISTORIC | | | |
| SURVEYDATE | 11/30/2007 | | | |
| SURVEYAREA | NAPERVILLE | | | |
| 214 NOR | NORTH | | | |





DIGITAL PHOTO ID

DIGITAL PHOTO ID2 \Images\north21 4(2).jpg

\Images\north21 4.jpg DIGITAL PHOTO ID3

DIGITAL PHOTOID4 \Images\north214(3).j

\Images\north214(4).j