

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

**City of NAPERVILLE**  
ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

**STREET #** 5

**STREET** N. COLUMBIA STREET

---

**ADDITIONAL PHOTOS OR INFORMATION**

*Alterations*

House recently renovated (received Illinois property tax assessment freeze)--large 1.5 story rear addition; replacement siding and shingles; replacement knee brackets and bracing; replacement windows in original openings (window under front gable was probably added when the attic was built out, before the latest renovation); replacement front stoop and entry canopy; north dormer addition

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southwest corner of Columbia and Benton; front and north sidewalks; side driveway; similar setbacks; mature trees; rear picket fence

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Northeast corner of Columbia and Benton; front and south sidewalks; side driveway; similar setbacks; mature trees; front plantings

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Benton and Columbia; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS** Chain of title for property (from Naperville Heritage Society Address Files) indicates house was built between 1905 & 1916. See continuation sheet.

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME** Schuler, Charles Royal House

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER** Kiest, Charles

**ARCHITECT SOURCE**

**HISTORIC INFO** According to history of house located in address files at Naperville Heritage Society, Charles Schuler and his wife were Chicago natives. Charles worked as an electrical engineer for Commonwealth Edison.

**PERMITS** Historic photos of house show that it was originally clad in stucco, with blind round arches above 1st story façade windows and round arch recessed front entry.

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear wood picket fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/6/2007

**SURVEYAREA** NAPERVILLE



**DIGITAL PHOTO ID** \Images\columbia012s.jpg

**DIGITAL PHOTO ID3** \Images\columbia012s(3).jpg

**DIGITAL PHOTO ID2** \Images\columbia012s(2).jpg

**DIGITAL PHOTO ID4** \Images\columbia012s(4).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear picket fence

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**



**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; partial driveway; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear picket fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**


**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southwest corner of Franklin and Columbia; front and north sidewalks; rear driveway; similar setbacks; mature trees; rear & south picket fence

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS** 1926 and 1943 Sanborn Maps (sheets 7 and 12) show full width front porch on house.

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear chain link fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Franklin and Columbia; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fencing

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**


**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Northwest corner of Columbia and Van Buren; front and south sidewalks; rear driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Map of Sears-Roebuck Kit home locations in NHS file (called "Sears Homes") indicates that this is a kit home. More research needed to verify this.

**PERMITS**

**LANDSCAPE** Northeast corner of Columbia and Van Buren; front and south sidewalks; rear alley; large north side yard; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southwest corner of Columbia and Van Buren; front and north sidewalks; rear driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS** 1926 Sanborn Map shows building without rear addition.

**LANDSCAPE** Northeast corner of Columbia and Franklin; front and south sidewalks; rear alley; rear wood fence; similar setbacks; mature trees

**COA DATE**


**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Columbia and Van Buren; front sidewalk; rear driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fence

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; large north side yard; front sidewalk; rear alley; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; house on slight rise, w/ stone retaining wall; rear ally; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; large north side yard; front sidewalk; side driveway; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; mature trees; large (double) lot; rear wood fence

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Northwest corner of Columbia and Chicago; front and south sidewalks; rear driveway; privacy plantings; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET #** 130

**STREET** N. COLUMBIA STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Significant Features*

Steep front gable bay with north side gable bay; projecting front entry and window bay; classical segmental arch entry canopy with fluted engaged columns; segmental arch leaded glass transom; historic door and sidelights; historic windows; scrolled brackets under eaves; shed canopy over north side entry

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley and side driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**

**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear wood fencing; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Columbia and School; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** FOR SALE

**PERMITS**

**LANDSCAPE** Northwest corner of Columbia and School; front and south sidewalks; rear driveway; rear fencing; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/5/2007

**SURVEYAREA** NAPERVILLE



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN


LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees (very wooded lot)

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

**STREET #** 219

**STREET** N. COLUMBIA STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

Aluminum siding under eaves; wood shingles under gables and on dormers; stucco cladding; front dormer enlarged with replacement windows; replacement windows in original openings; window bay addition (south); green house window (south); fixed shutters; greenhouse window on south elevation; turned wood columns on porch; two story rear addition

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; rear alley; front sidewalk; rear picket fence; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Columbia and North; front and north sidewalks; rear driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**