

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET # 415  
 DIRECTION E  
 STREET FRANKLIN  
 SUFFIX AV  
 PIN 0818307010  
 LOCAL SIGNIFICANCE RATING PS  
 POTENTIAL IND NR? (Y or N) N  
 Contributing to a NR DISTRICT? C  
 Contributing secondary structure? -  
 Listed on existing SURVEY? Local District; NR District



**GENERAL INFORMATION**

CATEGORY building CURRENT FUNCTION Domestic - single dwelling  
 CONDITION excellent HISTORIC FUNCTION Domestic - single dwelling  
 INTEGRITY minor alterations and addition(s) REASON for SIGNIFICANCE Good, intact example of American Foursquare type.  
 SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION American Foursquare PLAN Rectangular  
 DETAILS NO OF STORIES 2.5  
 BEGINYEAR c. 1915 ROOF TYPE Hipped  
 OTHER YEAR ROOF MATERIAL Asphalt - shingle  
 DATESOURCE Surveyor FOUNDATION Concrete - block  
 WALL MATERIAL (current) Wood PORCH Full front enclosed  
 WALL MATERIAL 2 (current) WINDOW MATERIAL Wood  
 WALL MATERIAL (original) Wood WINDOW MATERIAL  
 WALL MATERIAL 2 (original) WINDOW TYPE Double & single hung; hop  
 WINDOW CONFIG 1/1; 1-light; 5-light  
 SIGNIFICANT FEATURES Fared hipped roof with front and east side hipped roof dormers; hipped roof front porch enclosed with historic 5-light casement windows; historic 1/1 and 1-light wood windows  
 ALTERATIONS Replacement front door and steps (not historic); connector addition to rear garage (not historic)

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on north side of residential street; front sidewalk; east side alley; park to west; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

**City of NAPERVILLE**  
ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

**STREET #** 422

**STREET** E. FRANKLIN AVENUE

---

**ADDITIONAL PHOTOS OR INFORMATION**

*Alterations*

Replacement siding (not historic); front porch extended & later enclosed (historic); replacement windows in altered opening on wing (not historic); front porch enclosed with 9-light casement windows (c. 1925); 2 story rear addition; east side entry porch (c. 1950); skylights

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on south side of residential street; front sidewalk; side alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on north side of residential street; front sidewalk; side alley; similar setbacks; mature trees; rear wrought iron fence

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Northwest corner of Jefferson and Sleight; front and east sidewalks; rear driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**