

STREET # 516
 DIRECTION
 STREET SCHOOL
 SUFFIX ST
 PIN 0818141002
 LOCAL SIGNIFICANCE RATING C
 POTENTIAL IND NR? (Y or N) N
 Contributing to a NR DISTRICT? C
 Contributing secondary structure? -
 Listed on existing SURVEY? IHSS (O); Local District; NR



GENERAL INFORMATION

CATEGORY building CURRENT FUNCTION Domestic - single dwelling
 CONDITION good HISTORIC FUNCTION Domestic - single dwelling
 INTEGRITY minor alterations and addition(s) REASON for SIGNIFICANCE
 SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION L-Form PLAN L
 DETAILS Italianate NO OF STORIES 2.5
 BEGINYEAR c. 1870 ROOF TYPE Multi-gable
 OTHER YEAR ROOF MATERIAL Asphalt - shingle
 DATESOURCE Surveyor FOUNDATION Concrete - block
 WALL MATERIAL (current) Wood PORCH Front entry & front
 WALL MATERIAL 2 (current) WINDOW MATERIAL Wood
 WALL MATERIAL (original) Wood WINDOW MATERIAL
 WALL MATERIAL 2 (original) WINDOW TYPE double hung
 WINDOW CONFIG 1/1; 4/4
 SIGNIFICANT FEATURES front gable bay with side gable wing (looks like wing may be an early addition); historic 4/4 wood windows (probably not original)
 ALTERATIONS Vinyl siding; original window hoods removed when re-sided (see IHSS photo); replacement porches (roofs may be historic, but supports and base are not); replacement doors (1940s); 1 story rear addition

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on south side of residential street; house on slight rise with retaining wall; east side alley; similar setbacks; mature trees; front sidewalk

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET # 151-163

DIRECTION

STREET SCHOOL

SUFFIX ST

PIN 0818129011

LOCAL SIGNIFICANCE RATING NC

POTENTIAL IND NR? (Y or N) N

Contributing to a NR DISTRICT? NC

Contributing secondary structure? -

Listed on existing SURVEY? Local District; NR District



GENERAL INFORMATION

CATEGORY building CURRENT FUNCTION Domestic - multiple dwelling

CONDITION good HISTORIC FUNCTION Domestic - multiple dwelling

INTEGRITY not altered REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Townhouses-Mansard PLAN Rectangular

DETAILS NO OF STORIES 2

BEGINYEAR c. 1975 ROOF TYPE Mansard

OTHER YEAR ROOF MATERIAL Wood shingle

DATESOURCE Surveyor FOUNDATION Concrete

WALL MATERIAL (current) Wood - shingle/Stone PORCH

WALL MATERIAL 2 (current) Wood - vertical board WINDOW MATERIAL Aluminum

WALL MATERIAL (original) Wood - shingle/Stone WINDOW MATERIAL

WALL MATERIAL 2 (original) Wood - vertical board WINDOW TYPE sliding

WINDOW CONFIG 1-1

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northwest corner of School and Ellsworth; front and east sidewalks; rear parking lot; similar setbacks; mature trees; west alley

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southeast corner of School and Brainard; front and west sidewalks; building is at north end of main campus block; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Building featured in Naperville Heritage Housewalk brochure. See continuation sheet.

PERMITS

LANDSCAPE Northwest corner of Loomis and School; front and east sidewalks; west side parking lot

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS According to Sanborn Maps (1926) the building was originally used as a store.

LANDSCAPE Midblock on south side of residential street; front sidewalk; east side alley; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 421

STREET SCHOOL STREET

ADDITIONAL PHOTOS OR INFORMATION

Significant Features

Aluminum siding; replacement 1/1 vinyl windows in original openings; wood single light windows in altered openings; new entry and surround, may have originally had a front entry porch that was removed; glass block window on E side of front gable bay; E. side entry addition; 1 story E. addition; bay on W. side; vergeboard added in gable peak.

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on north side of residential street; front sidewalk; west side alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4