

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO See continuation sheet for historic postcard of house and owner information.

PERMITS

LANDSCAPE Southeast corner of Wright and North; double lot; front and north sidewalks; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Photograph of stenciling uncovered during rehab work says that house was built in 1905--no other information to substantiate that date.

PERMITS

LANDSCAPE Northeast corner of Wright and Chicago; oversized lot; front and south sidewalks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; side driveway; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME Kroehler, P.E., Carriage House

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Was originally carriage house for the P. E. Kroehler House

PERMITS

LANDSCAPE Midblock on south side of residential street; parking lot to east; mature trees

COA DATE

COA DECISION

PREPARER Lara Ramsey

PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS

SURVEYDATE 11/7/2007

SURVEYAREA NAPERVILLE



DIGITAL PHOTO ID	\\images\wright148n(3).jpg	DIGITAL PHOTO ID3	\\images\wright148n(3).jpg
DIGITAL PHOTO ID2	\\images\wright148n(2).jpg	DIGITAL PHOTO ID4	\\images\wright148n(4).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southwest corner of School and Wright; front and north sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET # 204
 DIRECTION N
 STREET WRIGHT
 SUFFIX ST
 PIN 0818143005
 LOCAL SIGNIFICANCE RATING S
 POTENTIAL IND NR? (Y or N) N
 Contributing to a NR DISTRICT? C
 Contributing secondary structure? C
 Listed on existing SURVEY? Local District; NR District



GENERAL INFORMATION

CATEGORY building CURRENT FUNCTION Domestic - single dwelling
 CONDITION excellent HISTORIC FUNCTION Domestic - single dwelling
 INTEGRITY Addition(s) REASON for SIGNIFICANCE Fine local example of Prairie Style with some Colonial details.
 SECONDARY STRUCTURE Detached garage
 Det. Gar. (NC)

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Prairie PLAN rectangular
 DETAILS Colonial Revival NO OF STORIES 2.5
 BEGINYEAR c. 1925 ROOF TYPE Hipped
 OTHER YEAR ROOF MATERIAL Asphalt - shingle
 DATESOURCE Surveyor FOUNDATION Not visible
 WALL MATERIAL (current) Brick PORCH Front entry
 WALL MATERIAL 2 (current) Wood - shingle WINDOW MATERIAL Wood
 WALL MATERIAL (original) Brick WINDOW MATERIAL
 WALL MATERIAL 2 (original) Wood - shingle WINDOW TYPE Double hung/casement/aw
 WINDOW CONFIG 6/1; 12-light; multi; 1/1
 SIGNIFICANT FEATURES Hipped roof with overhanging eaves and front central hipped dormer; front entry porch with hipped roof and square brick columns; historic wood windows; south/rear sun porch
 ALTERATIONS Two story rear addition

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northeast corner of Wright and School; front and south sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 205

STREET N. WRIGHT STREET

ADDITIONAL PHOTOS OR INFORMATION

Significant Features

Hipped roof with carved wood brackets (some with dropped pendants) under eaves; paneled wood frieze; 3-sided 2-story south window bay; front entry with double wood paneled doors, segmental arch transom, and incised wood surround; historic 2/2 and 1/1 wood windows with elaborate incised wood hoods and center wood keystones; south side entry with double wood door; porch with elaborate round arch wood openings

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO According to NR nomination, this residence was purchased by the Evangelical Theological Seminary in 1908 and moved to its present site in 1912 to serve as a dorm & married students apts.

PERMITS

LANDSCAPE Northeast corner of Wright and School, front and south sidewalks; rear driveway; similar setbacks; mature trees; Alternate address is 529 School Street

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATESOURCE PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southwest corner of North and Wright; front and north sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW TYPE

WALL MATERIAL 2 (original)

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; south side lot; rear/side wood fence; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northeast corner of Wright and Benton; front and south sidewalks; rear alley; rear and south picket fence; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southeast corner of Wright and Benton; front and north sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northwest corner of Wright and Benton; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear picket fence

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; side driveway

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear wrought iron fence

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southwest corner of Franklin and Wright; front and north sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southeast corner of Wright and Franklin; front sidewalk; rear driveway; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northwest corner of Wright and Van Buren; front and south sidewalks; rear driveway; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northeast corner of Wright and Van Buren; front and south sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northwest corner of Franklin and Wright; front and south sidewalks; rear driveway; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southeast corner of Wright & Van Buren; front and north sidewalks; side lot (south); rear driveway/alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southwest corner of Wright and Van Buren; front and north sidewalks; rear driveway; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear fencing

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 115

STREET S. WRIGHT STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Replacement siding (historic); wrought iron railing and concrete steps (not historic); fixed shutters (not historic); replacement 1/1 aluminum windows under gable (not historic); 3-sided south bay addition (historic); 1 story rear addition; replacement windows in original openings (historic); one story front bay and porch additions (not historic)

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 119

STREET N. WRIGHT STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

S. side addition between bays with interior stair & new entry (may be historic); replacement front porch (historic); 2 story rear addition; replacement windows on south gable and on 3rd floor under front gable (not historic); aluminum siding on 1st story and on rear addition (not historic); fixed shutters (not historic)

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; stone gate at rear; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID	<input type="text" value="\\images\wright119s.jpg"/>	DIGITAL PHOTO ID3	<input type="text" value="\\images\wright119s(3).jpg"/>
DIGITAL PHOTO ID2	<input type="text" value="\\images\wright119s(2).jpg"/>	DIGITAL PHOTOID4	<input type="text" value="\\images\wright119s(4).jpg"/>

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

WINDOW CONFIG

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO According to the owners, Mrs. Lillian Priem, who lived in the house from 19222 to 1960, was the first female chemistry professor at NCC.

PERMITS See continuation sheet for photograph of historic front entry. According to owners, the roof was originally hipped, & reconfigured in the 1930s during a 2-flat conversion. The cedar siding also dates from that time.

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4